

ABSTRACT OF COST

1. Restoration of road
Clts Quarry wide Rafe
(47) 85.29 m³
@ RS. 386.14/m³ RS. 32934/-

2. Maintenance of earthen
Shoulder (filling with fresh
selected Soil), Quarry wide
Rafe (47) 494.90 m²
@ RS. 57.36/m² RS. 28,387/-

3. Maintenance of Bitumen
mix Seal Surfacing Quarry
wide Rafe (47) 41 m²
@ RS. 41.58/m² - RS. 11,177/-
272.62

$$\begin{array}{r} 39564 = n \\ 72498 = \end{array}$$

[illegible]

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				10/10/21	100,288
B. Maintenance of road					
8.75 wide Road - (52)					
1.80km @ RS. 1076.8/km					1940
C. Maintenance of 200m and 100m stone bridge					
(51) - 1.80km.					
@ RS. 726				15/11/21	RS. 1308
					RS. 105536
Add 1-1. Labour class					RS. 10552
Add 12-1. G.S.T					RS. 12,664
					RS. 119255
<i>Chk</i>	9/14/24	<i>Shikhar</i>	9/14/24	<i>Chk</i>	15/05/24
Material Statement					
(1) E/W 1162.25m ³					
@ RS. 23.78/m ³					RS.
(2) chp. 2.22m ³					
@ RS. 470.04/m ³					RS.
(3) Puttuman					0.16m ³
Puttuman material					
Site -					3366m ³
Puttuman Consumption on Site -					0.16m ³
Puttuman Balance -					3.206m ³
<i>Chk</i>	9/14/24	<i>Shikhar</i>	9/14/24		

Continuation