

Kyapur Nithurto to Tassapur Sherat Nagar

Schedule XLV Form No. 134.

Agency - Smt Vinidu Devi

DIVISION

Nashat

SUB-DIVISION

MMGsy (sc)

Measurement Book

m. B. No. - 1017



[illegible]

ABSTRACT of Cost

- | | | | |
|-----|---|--------|---------|
| (1) | Restoration of rain cul
into SDI - | | |
| | 20.35 m ² (MMBP 23) | | |
| | at 395.76/m ³ - | 8054.2 | |
| (2) | Maintenance of center
shoulder - | | |
| | 114.00 m ² (MMBP 23) | | |
| | at 59.28/m ³ - | 6758.1 | |
| (3) | Patch repair over
bituminous surface - | | |
| | 7.03 m ² (MMBP 23) | | |
| | at 170.48/m ³ - | 1199.1 | |
| | | | 16011.0 |

