

UTSNY

**Schedule XLV-Form No. 134**

Lobg ~~st~~ Naikachit, Road.

E.E. Road, Pongauli **DIVISION**

Divya Bhushan

Siddhanta **SUB-DIVISION**

**Measurement Book**

M.B.No-827

| Particulars                                                             | Details of actual measurement                                                                            |         |       |        | Contents of area     |
|-------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|---------|-------|--------|----------------------|
|                                                                         | No.                                                                                                      | L.      | B.    | D.     |                      |
| Name of work - Construction of road from Laba to Nanka Dikhal G.T. way. |                                                                                                          |         |       |        |                      |
| Name of Agency - Smt. Divya Shakti                                      |                                                                                                          |         |       |        |                      |
| Agreement No. - 31/SB/2018-19                                           |                                                                                                          |         |       |        |                      |
| Date of commencement - 18.7.2018                                        |                                                                                                          |         |       |        |                      |
| Actual Date of Completion - 13/1/2019                                   |                                                                                                          |         |       |        |                      |
| 1/1                                                                     | Restoration of road cut with soil clear the loose soil beneath.                                          |         |       |        |                      |
|                                                                         | 1x                                                                                                       | 28.1m   | 0.9m  | 0.45m  | 11.32m <sup>2</sup>  |
|                                                                         | 1x                                                                                                       | 22.5m   | 0.9m  | 0.3m   | 6.075m <sup>2</sup>  |
|                                                                         | 1x                                                                                                       | 24.0m   | 0.9m  | 0.4(m) | 8.64m <sup>2</sup>   |
|                                                                         |                                                                                                          |         |       |        | 26.095m <sup>2</sup> |
| 1/2                                                                     | Maintenance of earthen shoulder making up loss of materials on shoulder to the design level. . . . / (1) |         |       |        |                      |
|                                                                         | 2x                                                                                                       | 30.0m   | 0.9m  |        | 54.0m <sup>2</sup>   |
|                                                                         | 2x                                                                                                       | 13.0m   | 0.9m  |        | 23.4m <sup>2</sup>   |
|                                                                         | 2x                                                                                                       | 2x30.0m | 0.75m |        | 90.0m <sup>2</sup>   |
|                                                                         | 1x                                                                                                       | 18.0m   | 0.9m  |        | 16.2m <sup>2</sup>   |
|                                                                         |                                                                                                          |         |       |        | 183.6m <sup>2</sup>  |

Continuation



| Particulars                                             | Details of actual measurement |    |    |    | Contents of area |
|---------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                         | No.                           | L. | B. | D. |                  |
| ABSTRACT of Cost                                        |                               |    |    |    |                  |
| 1/2 Restored of road                                    |                               |    |    |    |                  |
| cut - 1                                                 |                               |    |    |    |                  |
| 26.095 m <sup>2</sup> vide TMS for 34                   |                               |    |    |    |                  |
| cut to 25.92 m <sup>2</sup> @ 348 = 16 / m <sup>2</sup> |                               |    |    |    | 9024 =           |
| 1/2 Maintenance of earthen                              |                               |    |    |    |                  |
| shoulder - 1                                            |                               |    |    |    |                  |
| 183.6 m <sup>2</sup> vide TMS for 34                    |                               |    |    |    |                  |
| cut to 144.05 @ 52.09 / m <sup>2</sup>                  |                               |    |    |    | 7501 =           |
| 3/7 Maintenance of H.P.                                 |                               |    |    |    |                  |
| Culvert - 1                                             |                               |    |    |    |                  |
| 2 = vide TMS for 35                                     |                               |    |    |    |                  |
| CB 1072 = 18 each @ 2144 =                              |                               |    |    |    |                  |

|                                   |                            |  |  |  |            |
|-----------------------------------|----------------------------|--|--|--|------------|
| 1/9                               | Maintenance of road        |  |  |  |            |
|                                   | side - 1                   |  |  |  |            |
| 0.75 m                            | vide TMS for 35            |  |  |  |            |
|                                   | CB 1038.35 / plant         |  |  |  | 777 =      |
| 5/14                              | Trim of grass              |  |  |  |            |
|                                   | and weeds - 1              |  |  |  |            |
| 330.0 m <sup>2</sup>              | vide TMS for 35            |  |  |  |            |
|                                   | CB 2208 / m <sup>2</sup>   |  |  |  | 686 =      |
|                                   |                            |  |  |  | 20.132 =   |
| Less 10.07 @ 300 / m <sup>2</sup> |                            |  |  |  | 2013.00    |
|                                   |                            |  |  |  | to 18119 = |
| 10/2/2019                         | Malshuk                    |  |  |  |            |
|                                   | DE/w- 25.92 m <sup>2</sup> |  |  |  |            |
|                                   | 10/2/2019                  |  |  |  |            |

Continuation