

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, वायसी।

पत्रांक 970-(3130)

वायसी / दिनांक 10/05/2024.

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, वायसी।

सेवा में,

नोडल पदाधिकारी,
MR 3054 नई अनुरक्षण नीति 2018,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय: शीर्ष MR 3054 नई अनुरक्षण नीति 2018 अंतर्गत पथ में कराये गए कार्य के विरुद्ध अधियाचना भेजने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि शीर्ष MR 3054 नई अनुरक्षण नीति 2018 अंतर्गत पथ में कराये गए कार्य के विरुद्ध अधियाचना इस पत्र के साथ समर्पित की जा रही है।

विश्वासभाजन,


10/5/24

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, वायसी।

Vivelk Kr.
10/05/24.

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, Baisi

Requisition Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division- Baisi (Purnia)

Sl. no.	Batch no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (in lakh)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/PU/BA/23/001	Futani Hat To Mungra Piyaji	21105413010	87/01.06.22	3.702	232.278	195.42563	34.25085	01/MBD/2023-24	9.09.24	-	2331	25.00	5.02	0.00	0.00	195.38258	
Total																	195.38258	

[Signature]
Divisional Accounts Officer,
Rural Works Department,
Works Division, Baisi
(Purnia)

[Signature]
Executive Engineer
Rural Works Department
Works Division, Baisi
(Purnia)

Vivek Mr.
10/05/24.

***FORM GFR 19-A**
(See Government of India's decision (I) below rule- 150)
Form of Utilization certificate up to the month of March 2023
PIU: - E.E RWD(W)DIV-Baisi

SL.NO.	Name of Schemes	Updated Sanction No.& Date with Amount (In Lacs)	Amount received (In Lacs)	Particulars
1	2	3	4	5
1	New Maint. Policy-2018 (MR)	Lt no-16 dated 12.02.2024	Certified that out of Rs. 454.10257 Lacs of grants-in-aid sanctioned during the years 2023-24 in favour of Executive Engineer R. W. D. Works Division, Baisi sum of Rs. 420.96531 Lacs has been utilized for the purpose of New Maint. Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 33.13726 Lac remaining unutilized at the end of the period under report.	
		TOTAL	454.10257	

2. Certified that I have satisfied myself that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled, are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of checks exercised: -

- Works has been supervised by Executive Engineer / Superintending Engineer.
- Periodic as inspection has been conducted by Executive Engineer / Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer.
- All other codal formalities have been observed.

3. Physical Progress achieved: -

- Construction of Road Works.
- Construction of CD Works.

[Signature]
DIVISIONAL ACCOUNTS OFFICER

R.W.D. Works Division, Baisi

[Signature]
EXECUTIVE ENGINEER

R.W.D. Works Division, Baisi

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बायसी।
Email - twdbaysi@gmail.com

प्रमाण पत्र


प्रमाणित किया जाता है कि पथ- Futani Hat To Mungara Piyaji,
Project ID- 21105413010 का सभी अवयवों की जाँच शत प्रतिशत कनीय अभियंता द्वारा किया
गया है। सहायक अभियंता द्वारा सभी अवयवों की 50 प्रतिशत से अधिक जाँच किया गया है।
अधोहस्ताक्षरी द्वारा 10 प्रतिशत अवयवों की जाँच की गई है।


21/03/24

कनीय अभियंता


21/03/24

सहायक अभियंता


21/03/24

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बायसी।

Lab Job number :59

Date :18-03-2024

Name of Customer :Bol Bum Constructions

Name of Work/ Road :Futani Hat To Mungara Piyaji

Sr.no	Location of test (in km)	Corrected U.I value (mm/km)	Road catagory
1	0.100	2787	G
2	0.200	2400	G
3	0.300	2593	G
4	0.400	2497	G
5	0.500	2303	G
6	0.600	2400	G
7	0.700	2303	G
8	0.800	2206	G
9	0.900	2593	G
10	1.000	2303	G
11	1.100	2884	G
12	1.200	2497	G
13	1.300	2303	G
14	1.400	2303	G
15	1.500	2400	G
16	1.600	2497	G
17	1.700	2787	G
18	1.800	2303	G
19	1.900	2690	G
20	2.000	2400	G
21	2.100	2593	G
22	2.200	2400	G
23	2.300	2690	G
24	2.400	2303	G
25	2.500	1818	G
26	2.600	1818	G
27	2.700	2109	G
28	2.800	1915	G
29	2.900	2206	G
30	3.000	2109	G
31	3.100	1915	G
32	3.200	2206	G
33	3.300	2497	G
34	3.400	2109	G
35	3.500	1624	G
36	3.600	2109	G
37	3.700	2400	G
Average IRI Value		2331.62	

Sarish
SE 21/03/2024

As
21/03/24

Lab Job number :59
Date :18-03-2024

Name of Customer :Bai Bum Constructions
Name of Work/ Road :Futani Hat To Mungara Piyaji

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
18/3/24	8:48:27	59	0.1	180	0	2800	2787	G	26.01758	87.80053	Normal
18/3/24	8:48:27	59	0.1	240	20.2	2400	2400	G	26.01850	87.80057	Normal
18/3/24	8:49:2	59	0.1	260	20.3	2600	2593	G	26.01905	87.80021	Normal
18/3/24	8:49:2	59	0.1	250	20.2	2500	2497	G	26.01968	87.79988	Normal
18/3/24	8:49:2	59	0.1	230	20.2	2300	2303	G	26.02053	87.80009	Normal
18/3/24	8:49:37	59	0.1	240	20.2	2400	2400	G	26.02139	87.80059	Normal
18/3/24	8:50:0	59	0.1	230	10.1	2300	2303	G	26.02209	87.80108	Normal
18/3/24	8:50:13	59	0.1	220	20.2	2200	2206	G	26.02298	87.80124	Normal
18/3/24	8:50:13	59	0.1	260	20.2	2600	2593	G	26.02387	87.80136	Culvert
18/3/24	8:50:48	59	0.1	230	20.2	2300	2303	G	26.02394	87.80083	Curve
18/3/24	8:51:0	59	0.1	290	10.1	2900	2884	G	26.02470	87.80025	Normal
18/3/24	8:51:23	59	0.1	250	20.2	2500	2497	G	26.02555	87.80008	Normal
18/3/24	8:51:23	59	0.1	230	20.2	2300	2303	G	26.02639	87.79986	Normal
18/3/24	8:51:23	59	0.1	230	30.3	2300	2303	G	26.02721	87.79972	Normal
18/3/24	8:52:0	59	0.1	240	30.3	2400	2400	G	26.02806	87.79926	Curve
18/3/24	8:52:0	59	0.1	250	30.3	2500	2497	G	26.02824	87.79847	Normal
18/3/24	8:52:0	59	0.1	280	30.3	2800	2787	G	26.02737	87.79823	Normal
18/3/24	8:52:34	59	0.1	230	30.3	2300	2303	G	26.02678	87.79769	Curve
18/3/24	8:52:34	59	0.1	270	30.3	2700	2690	G	26.02686	87.79692	Normal
18/3/24	8:53:9	59	0.1	240	10.1	2400	2400	G	26.02609	87.79658	Normal
18/3/24	8:53:9	59	0.1	260	10.1	2600	2593	G	26.02570	87.79664	Normal
18/3/24	8:54:20	59	0.1	240	10.1	2400	2400	G	26.02448	87.79539	Normal
18/3/24	8:54:20	59	0.1	270	20.2	2700	2690	G	26.02404	87.79613	Speed Breaker
18/3/24	8:55:0	59	0.1	230	10.1	2300	2303	G	26.02358	87.79556	Curve
18/3/24	8:55:30	59	0.1	180	10.1	1800	1818	G	26.02371	87.79475	Normal
18/3/24	8:56:0	59	0.1	180	20.2	1800	1818	G	26.02293	87.79433	Normal
18/3/24	8:56:6	59	0.1	210	20.2	2100	2109	G	26.02221	87.79372	Normal
18/3/24	8:56:6	59	0.1	190	30.3	1900	1915	G	26.02150	87.79325	Normal
18/3/24	8:56:43	59	0.1	220	30.3	2200	2206	G	26.02073	87.79305	Normal
18/3/24	8:56:43	59	0.1	210	30.3	2100	2109	G	26.02004	87.79249	Normal
18/3/24	8:57:0	59	0.1	190	30.3	1900	1915	G	26.01934	87.79195	Normal
18/3/24	8:57:0	59	0.1	220	30.3	2200	2206	G	26.01913	87.79104	Normal
18/3/24	8:57:16	59	0.1	250	20.2	2500	2497	G	26.01926	87.79005	Normal
18/3/24	8:57:16	59	0.1	210	20.2	2100	2109	G	26.01942	87.78910	Normal
18/3/24	8:57:53	59	0.1	160	20.2	1600	1624	G	26.01952	87.78831	Normal
18/3/24	8:58:0	59	0.1	210	10.1	2100	2109	G	26.01985	87.78744	Normal
18/3/24	8:58:27	59	0.1	240	20.2	2400	2400	G	26.02029	87.78655	Normal

$$y = 0 * x^2 + 0.969 * x + 74.60$$

$$x = 2400$$

$$y = 2400$$


(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

Savitri
21/03/2024
or

Amul
21/03/24
Am

Amul
21/03/24
EE

File : E:\Bump Integrator\Baisa\Futani Hat To Mungara Piyaji\18030859.Xls. Section No. : 59. Eqn : $Y = 0 * X^2 +$
 Name of Customer : Bol Bum Constructions, Name of Work/ Road : Futani Hat To Mungara Piyaji. Lab Job number



Soil/26
 21/03/24

Paul
 21/03/24
 42