

				1st year Maintenance bld.
				<u>Abstract of cost.</u>
				(1/1) Restoration of Rain
				cut - - - - - at,
				03.679 m ² Hydrep (49) TmB
				98.72 m ² chs 404.06/m ² Rs 39888 =
				(2/2) Making up of Germal/
				shoulders - - - at,
				206.0 m ² Hydrep (49) TmB
				chs 61.28/m ² Rs 12418 =
				(3/5) patch repair over
				bedroomed surface
				width 20 mm - - - at,
				18.30 m ² Hydrep (50) TmB

Material inventory

ifw: — 98.72 m³

Strom- chips: — 0.468 m³

Bildungen (S-90): — 37.0 kg

consulation (R-1): — 5.0 kg

AK
25-01-24
JK

Baurall
23-3-24


23/3/24
 Executive Engineer
 RWD Works Division
 Manjhaul Bakhari