

5th year maintenance

58

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W- Rahimpur - Bishunpur Jagadishpur					
PMGSY path at Paschim Ahir Tola.					
Agency - Sri Raju Kumar Singh					
DOA - 30.03.2017					
DOAC - 11.01.2019					
Agreement - 12/MMGSY(WB)/MAD/2018-17					
① Restoration of rain culs do do all job -					
16x4.50x1.50x0.30 = 32.40					
19x7.00x1.80x0.30 = 71.82					
32x1.80x1.50x0.30 = 25.92					
5x22.00x1.20x0.30 = 39.60					
11x1.80x1.10x0.30 = 6.654					
					169.74 m ³
@ Rs 318.07/m ³					Rs 53989.00
② Making up shoulder do do all job -					
28x4.50x1.10 = 138.60					
34x2.20x1.30 = 97.24					
30x11.00x1.50 = 495.00					
8x22.00x1.20 = 211.20					
					942.04 m ²
@ Rs 48.62/m ²					Rs 45802.00
③					Rs

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
BIF amount -				R ₃	
③ Repair of pot holes with BM 75 mm do do all job -					
4 x 1.80 x 1.10 x 0.075 = 0.59					
7 x 1.20 x 1.50 x 0.075 = 0.95					
4 x 4.50 x 1.20 x 0.075 = 1.62					
8 x 11.00 x 1.30 x 0.075 = 8.58					
			11.74 m ³		
@ R _{9921.26/m³}				R _{116476.00}	
④ Repair with 13.2mm surface dressing do do all job -					
4 x 1.80 x 1.10 = 7.92					
7 x 1.20 x 1.50 = 12.60					
4 x 4.50 x 1.20 = 21.60					
8 x 11.00 x 1.30 = 114.40					
			156.52 m ²		
@ R _{93.77/m²}				R _{14677.00}	
⑤ Repair with 6.5mm surface dressing do do all job -					
area same as item ④ i.e					
27 x 156.52 m ² @ R _{89.61/m²}				R _{14026.00}	
⑥ Maint of HP Culvert do do all job -					
03 Nos					
@ R _{912.51/each}				R _{2738.00}	
				R ₃	

Continuation