

ਅਗਰਲਾਹ - SH 73 ਪੰਜਾਬ ਮੁਸਤਕ ਟੋਨੀ

M.B NO- 484

484

~~M.N. 25X~~
Schedule XLV-Form No. 134

JK

Farm Survey Committee
Labour Work Department
Works Division Maharashtra

DIVISION

MIS J.K and company

मरावड

SUB-DIVISION

Agrimment No 25/16-02-2019

MEASUREMENT BOOK

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>3rd yr Maintenance</u>					
Name of Work — SH-73 Se Bahaduli					
To Bahaduli Kumbhar Toli					
Name of Agency — J.K.L Company					
Ago. No. 25/MHGSY/SAD/ 2018-19.					
Date of commencement — 16.02.2019					
Date of Actual Completion — 03.09.2019					
Period — 03.09.21 to 02.09.22					
Date of Entry — 02.09.2022					
<u>Item of work:</u>					
J.10.1 — Restoration of Raincuts/ of Rain cuts/erosions with soil etc.					
2x2x 30x 0.82x 0.30 = 29.52					
2x2x 30x 0.78x 0.30 = 28.08					
1x2x 30x 0.70x 0.30 = 11.34					
					68.94 m ³
J.10.02 — Maintenance of Road					
Sign etc — 1 km.					
					0.15 Km.
J.10.03 — Maintenance 200 m and km stones.					
					0.18 Km.
02/09/22					03/09/22
JKL					MZ

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Material statement -</u>					
(1) Earth -	68.94	y^3			
Qd 02/09/22					0.18 Km ²
J.E. H.S					
<u>Abstract of Cost</u>					
J.40.1 - Restoration of Rain					0.12 Km ²
Cuts/Bettanset/C					
Vide P.10.34 in T.M.B.					
$68.94 y^3 R - 352 = 21.4^3 R - 24281 = 00$					
J.40.02/09 - Maintenance of Roof					38.08
Stairs etc - C.R.F					38.25
Vide P.10.34 in T.M.B.					
0.150 Km ² R - 1067 = 44 R - 160 = 00					
J.40.03/10 - Maintenance of roof and Ram stone.					
Vide P.10.34 in T.M.B.					
0.18 Km ² R - 570 = 27 / Km ² R - 103 = 00					
R - 24544 = 00					
600 10 P Below R - 2454 = 00					
R - 22090 = 00					
Qd 02/09/22					
J.E.					
Qd 03/09/22					
AT					