

Bayani Tola (Ramdasi) to MH 31 peth (Nirman)

MMISY-SC.

n/i. Nirman Construction

Schedule XLV-Form No. 134

Main house

E.E.R.O.D. Patwari DIVISION

Patwari SUB-DIVISION

Executive Engineer
R.W.D. Works Dyn.

Patwari

Measurement Book

942.

4th year Maintenance

63

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work. Construction of road for Bayenitole (Pander) to K.H. 31					
Name of Agency Nirmal Construction & Engineering					
Agreement No. 33 SRS / MMGSY / 19-20					
Date of Commencement - 1/8/2019					
Actual Date of Completion - 30/9/2020					
1/	Restoration of road cut.				
	2x	30.0x	0.9x	0.3m	= 32.4m
	1x	18.1x	0.9x	0.3m	= 4.07m
	1x	17.5x	1.0x	0.3m	= 5.25m
	1x	24.2x	0.9x	0.3m	= 6.36m
	1x	21.3x	0.9x	0.3m	= 5.75m
	2x	30.0x	1.0x	0.3m	= 36.0m
	1x	17.0x	0.9x	0.3m	= 4.59m
	1x	15.2x	1.1x	0.3m	= 4.96m
	1x	18.8x	1.0x	0.3m	= 5.64m
	1x	27.9x	0.9x	0.3m	= 7.28m
	1x	29.1x	0.8x	0.3m	= 6.98m
					<u>133.57m</u>
2/	Maintenance of center shoulder				
					162.0m
	2x	30.0x	0.9x		= 54.0m

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					162.00
	1x	8.3	1.0		8.30
	1x	14.7	1.1		16.17
	1x	30.0	0.9		27.00
	1x	27.9	0.9		25.11
	1x	18.8	1.0		18.80
	2x	4x	30.0	1.0	240.00
	1x	14.5	0.9		13.05
	1x	18.7	1.0		18.70
	2x	3x	30.0	0.9	162.00
					745.13
3/3.	Repair of Poles Roles by removal of false				
	chills with 75mm				
	worn 6mm Apply				
	Bastard Emulsion				
	Pock mark				
	1x	7.5	1.6		12.00
	1x	5.3	1.2		6.36
	1x	8.2	1.8		14.76
	1x	3.2	1.5		4.80
	1x	9.2	1.7		15.64
	1x	8.6	1.5		12.90
					66.42
4/4.	Marker and furrow				
	wood picked up				
	up to Poles Roles				
	rectified Corrected				

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		Surface - 16.9			
7/5	1	5.2	1.3		6.76
	1	5.9	1.9		11.21
	1	6.8	1.2		8.16
	1	9.1	1.7		15.47
	1	7.5	1.2		8.76
	1	11.6	2.0		23.2
					<u>73.56</u>
5/5	Pothole repair & at road filled Pothole with 75mm coarse G.III 20mm P.C. bit Seal Coat - etc				
	As above quality of Int. (4/4) of AN. (64) -				66.42
6/7	Maintenance of H.P. Culvert -				2 m
7/9	Maintenance of road Sign. -				1.15 m
8/12	Cutting of Branch of Trees -				10 m
9/14	Trimming of grass and weeds -				
					6

Continuation

	4th year Mainline and.	
	<u>ABSTRACT OF COST</u>	
1/1	Restoration of rain cut - 1	
	133.57 ³ vido tons for 63	
	CR 380 = 52 for 50826	
1/2	Mainline gutter shoulder - 1	
	745.13 ¹ vido tons for 66	
	dated 1 742.5 ¹ CR 57 = 53 for 42716	
2/3	Repair of Potholes by removal of - 1	
	66.42 ¹ vido tons for 64	
	dated 1 60.49 ¹ CR 194 = 32 for 11754	
	Continuation	

$$\cos 1.05296$$

