

MS

[illegible]

P.11/24
15.11.24

Continuation

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
11357407 of cut & p					
5711 YOUNG MOUNT. BELL					
① Restoration of Raincuts					
76.96 m ³ vide TM13 P.N. (50)					
@ Rs. 332.04/m ³ — R.					25554.00
② Making up of Berms/shoulders stripping excess soil etc.					
583.32 m ² vide TM13 P.					
No. (51) @ Rs. 53.30/m ²					31031.00
③ Repair of pot holes filled with 75 mm					
7.24 m ³ vide TM13 P.N. (51)					
@ Rs. 374.31/m ³ — R.					2710.00
④ Patch repair on already filled pot holes with 75 mm BM etc.					
100.78 m ² vide TM13 P.N. (52)					
@ Rs. 244.95/m ² — R.					24686.00
⑤ Repair to pot holes and removal of loose materials, trimming of sides, cleaning etc.					
99.30 m ² vide TM13 P.N. (52)					
@ Rs. 263.54/m ² — R.					26170.00
⑥ Maint. of cut work					
04 Nos vide TM13 P.N. (52)					
@ Rs. 1131.64/each — R.					4527.00

Continuation

Attested

Prithvi
15.11.24

Scanned with CamScanner