

45757 A

of Road from Malkana Primary School to
a Mushari Tola
Schedule XLV-Form No.-134 MP/65/52

विभाग का नाम

DIVISION

ज. वि. क्षेत्र का नाम

ज. वि. नं.

मानिसाही

SUB-DIVISION

MEASUREMENT BOOK

खि. आशीश यादव

No. 701

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
[07] Cutting of Shrubs from Road way = 07 No					
[08] White Washing of Pongpet Wall of CD work.					
02X03X6.15X0.40X0.60 =					8.856
03X02X6.15X0.40 =					14.76
03X04X0.60X0.40 =					2.88
					26.49
					<u>26.49</u>
Rand 10-09-24 JR					
part 10/9/24 HE					

Abstract of cost					
[01] Restoration of Raincets/ Berms with Soil/Maximum					
vide-P-52 = 84.69 cum					
@ ₹ 412 = ₹ 34952 = 0					
[02] making up of Berms/Shoulder					
Stripping excess Soil from the Shoulder.					
vide-P-53 = 436.50 sqm					
@ ₹ 37 = ₹ 136.50 = 0					
					₹ 24940 = 0
[03] Repair of Pot holes filled with 75mm B.M.					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Qty vide P-52-43650					
5.48m3					
@ ₹57=136/Sqm					₹21940=
@ ₹10463=129/m3					₹57339=00
04 Patch Repair over Pot					
holes with 13-20 mm to					
0.09mm m.s.s					
Area vide P-53, 34th (53)					
= 73.06 Sqm					
@ ₹256=389/Sqm					
					₹18732=
05 Maintenance of CD work					
(HP Culvert) = 03 No					
@ ₹1109=667					₹3329=00
06 Cutting of branches of trees & Shrubs					
= 02 No					
@ ₹115=338					₹232=00
07 Cutting of Shrubs from Road way vide P-54=07 No					
@ ₹6=474 Each					₹45=00
08 White washing of Parapet wall of HP culvert.					
vide P-54 = 26.49m2					
@ ₹16=360/Sqm					₹433=00
Less 0.02% below					₹140002=00
as per Agreement					₹28=00
					₹139974=00
Raw 10-09-24 J.E					
10/9/24					
Continuation					