

4041245

MMGSY (Gen.)

Schedule XLV-Form No. 134

Punpun Suraksha Bandh to Koli

DIVISION

Uritola W/a Panchayat Bhawan Koli

Durgaskhan.

SUB-DIVISION

MB No - 7528

(1012-1 8111)

Measurement Book

31st year Maint Bill

Sch. XLV-Form No. 134

Ser. XLV - Form No. 13					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
Name of work - Panchayat					
Sarabha Bandh to Koli					
Uthri Jala via Panchayat					
Bhamburda Koli Durga					
Sthan under MH/457 (4th)					
Agency - Niraj Kumar					
Agree. No - 14/SBD/2022-23					
Date of Commencement - 19-09-2022					
Date of Actual Completion -					
- 14-09-2023.					

(1) Reformation of raincuts/

Berms with soil, moorum

3 X 5.25 X 1.05 X 0.30 -	4.96 m ³ .
4 X 4.05 X 0.75 X 0.27 -	4.46 m ³ .
5 X 4.50 X 1.00 X 0.30 -	6.75 m ³ .
18 X 5.00 X 1.00 X 0.30 -	24.00 m ³ .
6 X 4.95 X 1.50 X 0.28 -	10.71 m ³ .
5 X 6.00 X 1.25 X 0.30 -	13.50 m ³ .
	64.28 m ³ .

(2) Making up of Berms/

Shoulder

10 X 4.05 X 1.25 -	50.63 m ² .
8 X 7.50 X 1.15 -	69.00 m ² .
6 X 6.75 X 1.45 -	58.73 m ² .
8 X 5.65 X 1.25 -	56.80 m ² .
5 X 6.05 X 1.50 -	45.38 m ² .
7 X 6.15 X 1.05 -	45.20 m ² .
4 X 6.00 X 1.20 -	28.80 m ² .
	354.24 m ² .

Continuation



Scanned with OKEN Scanner

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ Repair of pot holes.					
filled with 75 mm WBM.					
$2 \times 5.05 \times 0.90 \times 0.10$					0.09 m ³
				lt.	0.09 m ³
④ Patch repair over					
pot holes with 20 mm					
premium carpet					
$2 \times 5.25 \times 2.20$					12.60 m ²
$4 \times 4.00 \times 2.00$					32.00 m ²
					44.60 m ²
				lt.	29.77 m ²
⑤ Patch repair over					
bituminous surface.					
same as item ④					29.77 m ²
⑥ crack sealing - filling					
of cracks and joints					
excluding "crocodile"					
cracking.					1250 m
⑦ Repair of isolated					
areas of damaged					
concrete pavement					
$5 \times 2.00 \times 0.50$					5.00 m ²
⑧ Maint ⁿ of C/D work.					1 No
⑨ Maint ⁿ of Ld. pipes					1.5 km
⑩ Maint ⁿ of 200 mm & up pipe					1.5 km
⑪ Cutting of branches of					
tree & shrubs					3 Nos.
⑫ Cutting of shrubs from					
set. way					1250 Nos.

Continuation



Particulars	Details of actual measurement				Quantity of area
	No.	L	B	H	
(13) cutting of ground level					
2 x 42 x 30.00 x 1.25					2835.00
(14) white washing of plaster					
making of work					
4 x 6.00 x 0.60					14.40 m ²
2 x 6.00 x 0.40					4.80 m ²
4 x 0.60 x 0.40					0.96 m ²
					20.16 m ²
Subt.					
10/11/14					
J.E.					

सहायक अभियंता
बालीग केव विभाग 3
कार्य अवर प्रमोटर, मेमोरियल

Abstract of cost.

(1) Restoration of roadways	
Burns	
64.35 m ² by vide TMBP (52)	
item (1) @ Rs. 386.14 / m ² - Rs. 24,850.00	
(2) Making up of Burnt	
Shoulder	
354.24 m ² by vide TMBP (52)	
Item (2) @ Rs. 57.36 / m ² - Rs. 20,319.00	
(3) Repair of potholes	
filled with 75 mm 4084	
0.09 m ³ by vide TMBP (52)	
item (3) @ Rs. 331.78 / m ³ - Rs. 29.55	
(4) Patch repair on	
pot holes with 20 mm	

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
premium carpet -					
29.77 m ² Qty vide TMBP (53)					
item (4) @ Rs. 253.87/m ² - Rs. 7558=					
5) Patch repair on					
bituminous surface.					
29.77 m ² Qty vide TMBP (53)					
item (5) @ Rs. 270.95/m ² - Rs. 8066=					
6) crack sealing - filling					
of cracks & joints -					
1250.00 m Qty vide TMBP (53)					
item (6) @ Rs. 3.96/m - 4950=					
7) Repair of isolated areas					
of damaged concrete					
pavement					
5.00 m ² Qty vide TMBP (53)					
item (7) @ Rs. 253.87/m ² - Rs. 1269=					
8) Maint ^y of C/D work.					
1 No Qty vide TMBP (53)					
item (8) @ Rs. 1130.67/No - Rs. 1131=					
9) Maint ^y of rot. bridge					
1.5 km Qty vide TMBP (53)					
item (9) @ Rs. 1077.81/km - Rs. 1617=					
10) Maint ^y of road & kerb post					
1.5 km Qty vide TMBP (53)					
item (10) @ Rs. 628.22/km - Rs. 942=					
11) Cutting of branches of					
trees & shrubs.					
3 Nos. Qty vide TMBP (53)					
item (11) @ Rs. 109.79/No - Rs. 329=					

Continuation

Scanned with CamScanner