

4044245

MMGSY (Gen.)

Schedule XLV-Form No. 134

Punpun Suraksha Bandh to Koli

DIVISION

Utritala W/a Panchayat Bhawan Koli

Durgasthan.

SUB-DIVISION

MB No - 7528

(1012-1 8411)

Measurement Book



31 year Maint Bill

Set XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Pimpri					
Sarabha Bandh to Koli					
Uthri Jala via Panchayat					
Bhamburda Koli Durga					
Sitapur via MH/457 (4th)					
Agency - Niroj Kumar					
Agree. No - 14/SBD/2022-23					
Date of Commencement - 19-09-2022					
Date of Actual Completion -					
				14-09-2023	

(1) Reformation of raincuts

Berms with soil, medium

3 x 5.25 x 1.05 x 0.30 -	4.96 m ³
4 x 4.05 x 0.75 x 0.27 -	4.46 m ³
5 x 4.50 x 1.00 x 0.30 -	6.75 m ³
18 x 5.00 x 1.00 x 0.30 -	24.00 m ³
6 x 4.95 x 1.50 x 0.28 -	10.71 m ³
5 x 6.00 x 1.25 x 0.30 -	13.50 m ³
	64.28 m ³

(2) Making up of Berms

Shoulder

10 x 4.05 x 1.25 -	50.63 m ²
8 x 7.50 x 1.15 -	69.00 m ²
6 x 6.75 x 1.45 -	58.73 m ²
8 x 5.65 x 1.25 -	56.80 m ²
5 x 6.05 x 1.50 -	45.38 m ²
7 x 6.15 x 1.05 -	45.20 m ²
4 x 6.00 x 1.20 -	28.80 m ²
	354.24 m ²

Continuation



Scanned with OKEN Scanner

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ Repair of pot holes.					
filled with 75 mm WBM.					
2 x 5.05 x 0.90 x 0.10					0.09 m ³
				lt.	0.09 m ³
④ Patch repair over					
pot holes with 20 mm					
premium carpet					
2 x 5.25 x 2.20 -					12.60 m ²
4 x 4.00 x 2.00 -					32.00 m ²
					44.60 m ²
				lt.	29.77 m ²
⑤ Patch repair over					
bituminous surface.					
same as item ④ -					29.77 m ²
⑥ crack sealing - filling					
of cracks and joints.					
excluding "crocodile"					
cracking.					1250 m
⑦ Repair of isolated					
areas of damaged					
concrete pavement					
5 x 5.00 x 0.50 m					5.00 m ²
⑧ Maint ⁿ of C/D work.					1 No
⑨ Maint ⁿ of Ld. pipes					1.5 km
⑩ Maint ⁿ of 200 mm & up pipe					1.5 km
⑪ Cutting of branches of					
tree & shrubs					3 Nos.
⑫ Cutting of shrubs from					
set. way					1250 Nos.

Continuation



Particulars	Details of actual measurement				Quantity of area
	No.	L	B	H	
(13) cutting of ground level					
2 x 42 x 30.00 x 1.25					2835.00
(14) white washing of plaster					
walls of C/O work					
4 x 6.00 x 0.60					14.40 m ²
2 x 6.00 x 0.40					4.80 m ²
4 x 0.60 x 0.40					0.96 m ²
					20.16 m ²
Subt.					
10/11/14					
J.E.					

सहायक अभियंता
बालीग कोठ विभाग 3
कार्य अवर प्रमोटर, गणतन्त्र

Abstract of cost.

- (1) Restoration of railway
Barns.
- 64.35 m³Qty vide TMBP (52)
- Item (1) @ Rs. 386.14 / m³ - Rs 24,885.00
- (2) Making up of Barns/
Shoulder.
- 354.24 m²Qty vide TMBP (52)
- Item (2) @ Rs. 57.36 / m² - Rs 20,319.20
- (3) Repair of potholes.
- filled with 75 mm 4084
- 0.09 m³Qty vide TMBP (52)
- Item (3) @ Rs. 331.78 / m³ - Rs 29.52
- (4) Patch repair on
pot holes with 20 mm.

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
premium carpet -					
29.77 m ² Qty vide TMBP (53)					
item (4) @ Rs. 253.87/m ² - Rs. 7558=					
5) Patch repair on					
bituminous surface.					
29.77 m ² Qty vide TMBP (53)					
item (5) @ Rs. 270.95/m ² - Rs. 8066=					
6) crack sealing - filling					
of cracks & joints -					
1250.00 m Qty vide TMBP (53)					
item (6) @ Rs. 3.96/m - 4950=					
7) Repair of isolated areas					
of damaged concrete					
pavement					
5.00 m ² Qty vide TMBP (53)					
item (7) @ Rs. 253.87/m ² - Rs. 1269=					
8) Maint ^y of C/D work -					
1 No Qty vide TMBP (53)					
item (8) @ Rs. 1130.67/No - Rs. 1131=					
9) Maint ^y of rot. bridge					
1.5 km Qty vide TMBP (53)					
item (9) @ Rs. 1077.81/km - Rs. 1617=					
10) Maint ^y of road & kerb post					
1.5 km Qty vide TMBP (53)					
item (10) @ Rs. 628.22/km - Rs. 942=					
11) Cutting of branches of					
trees & shrubs.					
3 Nos. Qty vide TMBP (53)					
item (11) @ Rs. 109.79/No - Rs. 329=					

Continuation

