

| Particulars                                                         | Details of actual measurement |    |    |    | Contents of area |
|---------------------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                                     | No.                           | L. | B. | D. |                  |
| 2nd year Maintenance                                                |                               |    |    |    |                  |
| from 03.08.2022 to 02.08.2023                                       |                               |    |    |    |                  |
| Name of Work: Maintenance of                                        |                               |    |    |    |                  |
| road from Bhatipur Awtarnagar                                       |                               |    |    |    |                  |
| Path to Gayray talga                                                |                               |    |    |    |                  |
| Gremis Path                                                         |                               |    |    |    |                  |
| Agency - Kumar Ravi                                                 |                               |    |    |    |                  |
| Agreement No - 18/SID/2020-21                                       |                               |    |    |    |                  |
| Date of start - 25.04.2020                                          |                               |    |    |    |                  |
| Actual date of completion 02.08.20                                  |                               |    |    |    |                  |
| Date of measurement 12/09/23                                        |                               |    |    |    |                  |
| 1. Restoration of drain line                                        |                               |    |    |    |                  |
| with Soil, Manure or                                                |                               |    |    |    |                  |
| Gravel                                                              |                               |    |    |    |                  |
| $1 \times 12.5 \times 2 \times 0.76 \times 0.30 = 5.70$             |                               |    |    |    |                  |
| $1 \times 11.60 \times 2 \times 0.60 \times 0.30 = 4.1$             |                               |    |    |    |                  |
| $1 \times 10.8 \times 2 \times 0.76 \times 0.30 = 9.87 \text{ m}^3$ |                               |    |    |    |                  |
| for 9.37 m <sup>3</sup>                                             |                               |    |    |    |                  |
| 2. Maintenance of Carthen                                           |                               |    |    |    |                  |
| Shoulder                                                            |                               |    |    |    |                  |
| $1 \times 14.25 \times 2 \times 0.80 = 22.8$                        |                               |    |    |    |                  |
| $1 \times 19 \times 0.76 = 14.44$                                   |                               |    |    |    |                  |
| 37.24 m <sup>3</sup>                                                |                               |    |    |    |                  |
| for 33.92 m <sup>3</sup>                                            |                               |    |    |    |                  |

Sch. XLV—Form No. 134

| Particulars | Details of actual measurement |    |    |    | Contents of area |
|-------------|-------------------------------|----|----|----|------------------|
|             | No.                           | L. | B. | D. |                  |

ABSTRACT OF COST1 Restoration of rain cutsWith Soil, Manure &Gravelvide item no (1) P.N. 41Qty = 9.37 m<sup>3</sup>@ 385 = 141 m<sup>3</sup>& 3618 = 132 Maintenance of PathShouldervide item no (2) P.N. 41Qty = 33.92 m<sup>2</sup>@ 57 = 36 m<sup>2</sup>1939.91& 1945.653 Patch repair overbituminous Surface overthin Premix Carpetvide item (3) P.N. 41Qty 6.07 m<sup>2</sup> @ 352 = 31 m<sup>2</sup>2138 = 524 Cutting of branches of11 treesvide item no (4) P.N. 42Qty: 1 Nos @ 109 = 74 m<sup>2</sup> & 109 = 745 Maintenance of Areavide item no (5) P.N. 42Qty = 14 Nos @ 674 = 37 m<sup>2</sup> & 9441 = 1817247.48& 17253 = 22Less 0.57 below (-)86.26 26.3

Continuation

17161.25

17166.25

17160.25

17167.25

124923.5