

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>15 year maintenance bill</u>					
Name of work - Genral Maintenance					
of road from Ganeshi					
pokhar to LOTS in					
HMCSB in Behaeshrit					
Agents - Binod Kumar					
Agreement No - SRD - 36 / 2020-21					
date of start					21/12/20
date of completion					20/6/21
actual date of completion					10/4/23
① Restoration of drain					
cut with 300 x					
1000 mm etc in dry					
5 x 4.0m x 1.0m x 0.30 =					6.0m <sup>2</sup>

4 x 4.0m x 0.90 x 0.30 =					4.32m <sup>2</sup>
Total =					23.82m <sup>2</sup>
② Maintenance of earthen					
shoulder in all					
6 x 4.0m x 1.0m =					24.0m <sup>2</sup>
9 x 5.0m x 1.20 =					54.0m <sup>2</sup>
9 x 6.0m x 0.90 =					48.60m <sup>2</sup>
4 x 4.0m x 1.0m =					16.0m <sup>2</sup>
Total =					142.60m <sup>2</sup>
③ patch repair over bituminous					
surface with 20mm					
porch carpet & deal cut					
4 x 3.0m x 0.90m =					10.80m <sup>2</sup>
2 x 2.0m x 0.60m =					1.60m <sup>2</sup>

Continuation Total = 12.40m<sup>2</sup>  
 Grand = 12.07m<sup>2</sup>

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4) Maintenance of Hems pipes quantity					0/1 No
(5) Maintenance & Road sign					0.05 KM
(6) Maintenance of 2m x 8 KM stone					0.06 KM
(7) cutting & Banning of Tree					02 No
(8) wheels washing of sample well					21.0 ML

ABSTRACT OF WORK				
(1) Restoration of Reinconcr. with T13. PSC 25/40 quantity = 23.82 M <sup>3</sup> @ 404 = 9661 M <sup>3</sup>				9625 = 10
(2) Maintenance of earthen shrub in cul. with T13. PSC 25/40 quantity = 142.60 M <sup>3</sup> @ 60 = 281 M <sup>3</sup>				8596 = 10
(3) Patch repair over bitumen new surface in cul. with T13. PSC 25/40 quantity = 12.07 M <sup>3</sup> @ 263 = 151 M <sup>3</sup>				3780 = 10
				CO TOTAL 22001 = 10

