



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

PLAN HEAD- FDR YEAR 2024

DISTRICT :- NALANDA
BLOCK :- KARAIPARSURAI

Estimate for Repair of Road breaches
(Damaged by Flood) for Motorability in T01
Link Road To Diyawan Bharthu Path

LENGTH OF ROAD (in Km)- 13.500 KM
DAMAGED LENGTH (in Km)- 0.0145 KM

ESTIMATED COST - 9.809 Lacs


SUBMITTED BY:
EXECUTIVE ENGINEER,
RWD WORKS DIVISION,
HILSA

प्रतिवेदन


1. शीर्ष:- **FDR**
2. पथ का नाम:- **Estimate for Repair of Road Breaches (Damaged by Flood) for Motorability in T01 Link Road to Diyawar Bharthu Path.**
- 3- **Damaged Length (In Km):-0.0145 KM**
4. प्रखंड:- **करायपरशुराय।**
5. प्राक्कलित राशि:- **9.809 लाख।**

उपर्युक्त पथ में वर्ष-2024 में आयी बाढ़ के कारण पथ के विभिन्न पथांशों में कटाव हो गया था। जिसके कारण आवागमन बाधित हो गया था जिसकी पुष्टि ड्रोन फोटोग्राफी एवं विडियोग्राफी से भी हुई है। जिसके उपरान्त विभागीय दिशा-निर्देशों के आलोक में आवागमन चालु करने के लिए ब्रिक बैट से भराई कराया गया।


तदनुसूच कार्य अंचल नालन्दा से स्वीकृति दर पर प्राक्कलन तैयार किया गया है।


23/10/24

कनीय अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रशाखा, करायपरशुराय।


23/10/24

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, करायपरशुराय


23/10/24

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, हिलसा।

Inspection Report For Flood Damage Report

Date : E.E, RWD, HILSA.

1 Name of PIUs : KARAI PAR SURAI / To Link road to Dr. Harnan Bharkhu Path

2 Name of Block/ Road :

A For Road :

1 Damage Location/ Chainage : 0.00km, 1.500km.

2 Damage Length : 0.0145 km

3 Nature of Damage : Road breach due to flood water.

4 Details of Restoration Works :

i Material being used in Restoration works : Brick Bat, Earth work, Hume pipe 1000mm

ii Equipments/ Tools being used in Restoration works : JCB, Tractor, static roller etc.

iii Procedure taken up in Restoration works : Immediate Restoration of traffic

iv Restored Length : 0.0145 km

B For Bridge :

1 Damage Location/ Chainage : N.A

2 Damage Length :

3 Nature of Damage :


4 Details of Restoration Works : N.A


i Material being used in Restoration works :


ii Equipments/ Tools being used in Restoration works :

iii Procedure taken up in Restoration works :

iv Restored Length :

Signature of JE / AE :  23/10/24
Executive Engineer
Rural Works Department
Works Division, Hilsa

 23/10/24
AE


Signature :  09.11.24
Executive Engineer
Rural Works Department
Works Division Harnaut

तकनीकी प्रतिवेदन

1. शीर्ष:- **FDR**
2. पथ का नाम:- **Estimate for Repair of Road Breaches (Damaged by Flood) for Motorability in T01 Link Road to Diyawar Bharthu Path.**
- 3- Damaged Length (In Km):- **0.0145 Km**
4. प्रखंड:- **करायपरशुराय।**
5. प्राक्कलित राशि:- **9.809 लाख।**

विभागीय पत्रांक-मु0अ0-8(अनु0 एवं उन्नयन) FDR-03-01/2024-106
दिनांक-05.11.2024 के अलोक में आज दिनांक-~~09.11.2024~~ को T01 Link Road to Diyawar Bharthu Path का निरीक्षण किया गया। निरीक्षण के क्रम में पाया गया कि वर्ष-2024-25 में आये बाढ़ के कारण उपर्युक्त पथ के क्षतिग्रस्त पथांश कुल-0.025 किमी0 में ब्रीक बैट भरते हुए पथ को मोटरेवल किया गया है। वर्तमान में इस पथ से आवागमन सुचारु रूप से हो रहा है।

तत्पश्चात् Temporary Restoration में किये गये कार्य का प्राक्कलन स्थल के अनुरूप है।


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, हरनौत।

GENERAL ABSTRACT OF COST

ESTIMATE FOR REPAIR OF ROAD BREACHES (DAMAGED BY FLOOD) FOR
MOTORIBILITY IN T01 LINK ROAD TO DIYAWAN BHARTHU PATH

DISTRICT - NALANDA

DIVISION - HILSA


BLOCK - KARAIPARSURAI

LENGTH OF ROAD (in Km)- 13.500 KM

SL. No.	Item of Work	Amount
1	BRICK BATS	8.306 Laes
2	HUME PIPE	1.502 Laes
	COST OF RESTORATION	9.809 Laes


23/10/24
Junior Engineer



23/10/24
Asstt. Engineer


23-10-24
Executive Engineer
Rural Works Department
Works Division, Hilsa

technically sanctioned for Rs. 9,809.40 (Rupees Nine
lakh eighty thousand and Nine hundred
including five year Maintenance Cost)

W. S. P.
26/11/24
Superintending Engineer
Rural Work Department
Work Circle, Nalanda

S. M. U.
26/11/24



Handwritten signature
 9/11/24
 A E

Handwritten signature
 9/11/24
 Executive Engineer
 Rural Works Department
 Works Division, Hilsa



Handwritten signature



[Signature]
 9/11/24
 A.E.

[Signature]
 9/11/24
 Executive Engineer
 Rural Works Department
 Works Division, Hilsa



[Signature]
 9/11/24
 A.E.

[Signature]
 9/11/24
 Executive Engineer



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

PLAN HEAD- FDR YEAR 2024

DISTRICT :- NALANDA

BLOCK :- KARAIPARSURAI

Estimate for Repair of Road breaches
(Damaged by Flood) for Motorability in T01
Link Road To Diyawan Bharthu Path

LENGTH OF ROAD (in Km)- 13.500 KM

DAMAGED LENGTH (in Km)- ०.७०५ KM

ESTIMATED COST -	5.808	Lacs
------------------	-------	------

SUBMITTED BY:
EXECUTIVE ENGINEER,
RWD WORKS DIVISION,
HILSA


Division, Hilsa

प्रतिवेदन

1. शीर्ष:- **FDR**
2. पथ का नाम:- **Estimate for Repair of Road Breaches (Damaged by Flood) for Motorability in T01 Link Road to Diyawan Bharthu Path.**
- 3- Damaged Length (In Km):- **0.405 Km**
4. प्रखंड:- **करायपरशुराय ।**
5. प्राक्कलित राशि:- **₹ 5.808 लाख ।**


उपर्युक्त पथ में वर्ष-2024 में आयी बाढ़ के कारण पथ के विभिन्न पथांशों में कटाव हो गया था। जिसके कारण आवागमन बाधित हो गया था जिसकी पुष्टि ड्रोन फोटोग्राफी एवं विडियोग्राफी से भी हुई है। जिसके उपरान्त विभागीय दिशा-निर्देशों के आलोक में अवागमन चालु करने के लिए ब्रिक बैट से भराई कराया गया।

तदनुसूच कार्य अंचल नालन्दा से स्वीकृति दर पर प्राक्कलन तैयार किया गया है।



23/10/24

कनीय अभियंता
ग्रामीण कार्य विभाग,

कार्य प्रशाखा, करायपरशुराय। कार्य अवर प्रमंडल, करायपरशुराय


23/10/24

सहायक अभियंता
ग्रामीण कार्य विभाग


23/10/24

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, हिलसा।

Inspection Report For Flood Damage Report

- Date : E.E, RWD, HILSA.
- 1 Name of PIUs : KARAI PAR SU RAI / To Link road to Di-
- 2 Name of Block/ Road : Hawan Bhatlu Path
- A For Road
- 1 Damage Location/ Chainage : 0.00km, 1.500km.
- 2 Damage Length : 0.0105 km.
- 3 Nature of Damage : Road breach due to flood water.
- 4 Details of Restoration Works
- i Material being used in Restoration works : Brick Bat, Earth work, Humaprae 1000mm
- ii Equipments/ Tools being used in Restoration works : JCB, Tractor, static Roller etc.
- iii Procedure taken up in Restoration works : Immediate Restoration of traffic
- iv Restored Length : 0.0105 km.
- B For Bridge
- 1 Damage Location/ Chainage : N.A
- 2 Damage Length : N.A
- 3 Nature of Damage : N.A
- 4 Details of Restoration Works
- i Material being used in Restoration works : N.A
- ii Equipments/ Tools being used in Restoration works : N.A
- iii Procedure taken up in Restoration works : N.A
- iv Restored Length : N.A

Signature of JE / AE

Executive Engineer
Rural Works Department
Works Division, Hilsa

Signature
23/10/24
AE


Signature
09.11.24
Executive Engineer
Rural Works Department
Works Division Hamaut

तकनीकी प्रतिवेदन

1. शीर्ष:- FDR
2. पथ का नाम:- Estimate for Repair of Road Breaches (Damaged by Flood) for Motorability in T01 Link Road to Diyawan Bharthu Path.
- 3- Damaged Length (In Km):- 4.015 Km
4. प्रखंड:- करायपरशुराय।
5. प्राक्कलित राशि:- 5.808 लाख।

विभागीय पत्रांक-मु0अ0-8(अनु0 एवं उन्नयन) FDR-03-01/2024-106
दिनांक-05.11.2024 के अलोक में आज दिनांक-09.11.2024 को T01 Link Road to Diyawan Bharthu Path का निरीक्षण किया गया। निरीक्षण के क्रम में पाया गया कि वर्ष-2024-25 में आये बाढ़ के कारण उपर्युक्त पथ के क्षतिग्रस्त पथांश कुल-0.025 किमी० में ब्रीक बेट भरते हुए पथ को मोटरेवल किया गया है। वर्तमान में इस पथ से आवागमन सुचारु रूप से हो रहा है।

तत्पश्चात् Temporary Restoration में किये गये कार्य का प्राक्कलन स्थल के अनुरूप है।


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, हरनौत।

GENERAL ABSTRACT OF COST

ESTIMATE FOR REPAIR OF ROAD BREACHES (DAMAGED BY FLOOD) FOR MOTORABILITY IN T01 LINK ROAD TO DIYAWAN BHARTHU PATH

DISTRICT - NALANDA

BLOCK - KARAIPARSURAI


DIVISION - HILSA

LENGTH OF ROAD (in Km)- 13.500 KM

SL. No.	Item of Work	Amount
1	BRICK BATS	5.808 Lacs
2	HUME PIPE	0.000 Lacs
	COST OF RESTORATION	5.808 Lacs


23/10/24
Junior Engineer


23/10/24
Asstt. Engineer


23-10-24
Executive Engineer
Rural Works Department
Works Division, Hilsa

technically sanctioned for Rs. 5,80,000 Rupees. Five lakh
eighty thousand and eight hundred only
including five year Maintenance Cost

W. T. Sengupta
Superintending Engineer
Rural Work Department
Work Circle, Malanda

Somv
26/11/24

