

MB NO:-3492

Const. of Road from Kishunpur Kotesar Path me

Schedule XLV-Form No. 134

Hasmatya ke whar to Muslim Basti tk.

Ashish Royan

DIVISION

MMMSY-SC

MB NO:-3492

SUB-DIVISION

To/01/24

Measurement Book

MMMSY-SC

1st Year Maintenance bill

33

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w - construction of road from kishampur Katedhar Path me Haymatiya Ke ghar to muslim Dasti tak.					
N/Agency - Atkith Ranjion.					
Agg No - 18/SBD/2020-21					
D.O.S - 1130.06.2021					
D.O.C - 12.03.2022					
① Restoration of raincut/Berm with soil. modrum etc					
					$10 \times 1.5 \times 0.50 \times 0.30 = 2.25 m^3$
					$5 \times 1.7 \times 0.50 \times 0.30 = 1.275 m^3$
					$= 3.525 m^3$
					Qty Limit = $3.38 m^3$
② Making up of Berm/Shoulder stripping excess soil.					
					$2 \times 6.50 \times 0.65 = 8.45 m^2$
					$2 \times 5.50 \times .55 = 6.05 m^2$
					$= 14.5 m^2$
					Qty Limit = $14.06 m^2$
③ Patch repair over bituminous surface with 20 mm					
					$2 \times 0.8 \times 1.2 = 1.92 m^2$
					Qty Limit = $1.88 m^2$
④ Maintenance of C/P work/slab					
					1.00 by 1.00 — 1.00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑤ Maintenance of road signs		0.06	XI	—	0.06 km
⑥ Maintenance of 200 m and km stn		0.07	XI	—	0.07 km
7-① cutting of branches of trees		81.00	XI	—	1.00
7-② cutting of shrubs from roadway		4.00	XI	—	1.00
7-③ Trimming of grass and weeds		2 x 0.75	X 0.4	=	0.60
			Qty limit	—	0.54 m ²

Abstract of cost

① Restoration of rain cut/Berms with soil. masonry etc.					
IMB/P-33	3.38	14.06	@ 386.4	=	1303.00
② Making up of berms/shoulder					
IMB/P-33	14.06	@	57.36	=	807.00
③ Patch repair over bitumens.					
IMB/P-33	1.88	@	349.81	=	656.00
④ Maintenance of C/P work					
IMB/P-33	1.00	@	2329.20	=	2329.00
⑤ Maintenance of road signs.					
IMB/P-35	0.06	@	1077.02	=	65.00

C/O-Rs 5160.00

[illegible]