INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD WO	MILL STAND A COLON
Name of Block/Road :- Sikh	Tengapur middle school se purab Qaichlin + Tengapur pipra mandal Tolq
1. Damage Location/Chainage :-	2500
2. Damage Length :- 40.70	M , 56 M
3. Nature of Damage (Length Wise)	(i) Breach:- Ore ach
	(ii) Crust Damage :-
	(iii) Only Flank Domago
whether traffic fully/Partialiy obstruc	cted :-
4. Details of Restoration:-	
(i) Material Being Used in Restoration	on: Local Sand, Bamboo, Ec Bags Brige Ba
(ii) Equipment/Tools Being Used in	on: - Local Sand, Bamboo, Ec Bags Brid (Ba Restoration Works: - Trace boy with Trolly, TCB R
(iii) Restored Length	In open Area:-
	In habitation Area:-
(iv) If Restoration work done in habi	itation Area give Reason :-
B. For Bridge (Size of Bridge/C	ulvert)
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttme Wing Wall/Approach Road Damage)	ent/):-
(5) Details of Restoration:-	
(i) Material Being Used in Restoration	on :-
(ii) Equipment/Tools Being Used in 1	Restoration Works :-
(iii) Restored Length :-	
Overall Grade of Restoration work	(Satisfactory/Insatisfactory) :- Sally Lad
or reduction work	k (Satisfactory/Unsatisfactory):- Satisfactory
	1 Jan Pliny
P/11/24	
	Signature of Inspector

(Official Seal)