

# INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-		EE RWA Works Division Anand	
Name of Block/Road :-		Tukhat / Turkeli Uda MDA Mai Bageshwari Masjid to Kojatikhari	
A. For Road			
1. Damage Location/Chainage :-		0.4km, 0.55km, 0.65km, 2.2km	
2. Damage Length :-		88 m	
3. Nature of Damage (Length Wise)		(i) Breach :- Breach damage	
		(ii) Crust Damage :- Crust damage	
		(iii) Only Flank Damage :-	
Whether traffic fully/Partially obstructed :- fully			
4. Details of Restoration :-			
i) Material Being Used in Restoration :- Local Sand, Bamboo Piling, Brick Bats etc			
ii) Equipment/Tools Being Used in Restoration Works :- Tractor with trolley, Roller, JCB			
iii) Restored Length		In open Area :-	
		In habitation Area :-	
iv) If Restoration work done in habitation Area give Reason :-			
3. For Bridge (Size of Bridge/Culvert)			
1) Damage Location/Chainage :-			
2) No. of Span Damage :-			
3) Length of Span :-			
4) Nature of Damage (Pier/Abutment/ Wing Wall/Approach Road Damage) :-			
5) Details of Restoration :-			
i) Material Being Used in Restoration :-			
ii) Equipment/Tools Being Used in Restoration Works :-			
iii) Restored Length :-			
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory			

14/11/24

Signature of Inspector  
(Official Seal)