INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- RIND ALL OLD	
Name of PIUs: RWD WORKS	DIVISION I NANGACHINIYA JIOWK MRLOJ-POD DUMARIYA PATH TOTINITAN SISHARI STUAN
A. For Road	JOWK STSHART STHAN
1. Damage Location / Chainage:	3800 - 3900M
2. Damage Length: 60 M	
3. Nature of Damage (length wise)	(i) Breach :- 15 M
	(ii) Crust Damage :- ACM
	(iii) Only Flank Damage
whether traffic fully/Partialily obstr	ructed fully obstanted.
4. Details of Restoration;	
(i) Material Being Used in Restorat	ion: Brick bate, Ec bag, Local Sand.
	in Restoration Works: Front End Loader, Roner
(iii) Restored length	In open Area :- 60 M
	In habitation Area :-
(iv) if Restoration work done in hal	oitation Area give Reason :
B. For Bridge (Size of Bridge / Cu	ılvert) _
1. Damage Location / Chainage :	
2. No. of Span Damage :-	
3 Length of Span	
Nature of Damage (Pier / Abutme	ent/Wing wall/Approach Road Damage) —
5. Details of Restoration :	
i) Material Being Used in Restorat	ion:
ii) Equipment / Tools being Used i	n Restoration Works :
iii) Restored length	In open Area :-
	In habitation Area :-
Overall Grade of Restoration Work	(Satisfactory / Unsatisfactory) Safisfactory.
A STATE OF THE STA	111401

CATION AND THE BOY

Signture of Inspector
(Official Seal)
Executive Engineer
RWD Works Division
BANKA-1