INSPECTION REPORT FOR MOTORABLE WORK

lame of PlUs:- RED WORKS	DIVISION, NAVGACHHIYA
lame of Block / Road :- ISHILE	DIVISION, NANGHCHMI YA PUR 1026-701 TO RAGHUNI TOLA VIA PUR MABDHAI TOLAC VRI)
L. For Koad	
. Damage Location / Chainage: 10	600-210019
Damage Length: A75 M	
3. Nature of Damage (length wise)	(i) Breach :- 1014
	(ii) Crust Damage : 400)
	(iii) Only Flank Damage 65 M
whether traffic fully/Partialily obstr	ucted Fully obstructed
	ion: Brick Batt, Rabbieh.
(ii) Equipment / Tools being Used i	n Restoration works were
(iii) Restored length	In open Area : 442 (
	In habitation Area:-
(iv) if Restoration work done in hat	oitation Area give Reason :
B. For Bridge (Size of Bridge / Cu	ılvert) —
1. Damage Location / Chainage :	
2. No. of Span Damage :-	
2 Length of Span	
4 Nature of Damage (Pier / Abutme	ent/Wing wall/Approach Road Damage)
5. Details of Restoration :	
(i) Material Being Used in Restorat	tion:
(ii) Equipment / Tools being Used	in Restoration Works:
(iii) Restored length	In open Area:-
	In habitation Area:-
	(Satisfactory / Unsatisfactory) Safisfactory.

Call 124 Tay 11/24

5hm/1/2

Signture of Inspector
(Officail Seal)
Executive Engineer
RWD Works Division
BANKA-1