

Schedule XLV-Form No. 134

Bilukas to Biluphan miskeisite!

missvles

Bonfitti

DIVISION

Halsaki

SUB-DIVISION

M. B-MD-1134

MEASUREMENT BOOK

Dharmeshwari. 719

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year maintenance					
N/w - Bitumen to Bitumen muohani					
Agency - Dhamadkhar Kurur Jha					
Ad No - 26 SBD/19-20					
Date of start - 25.01.2020					
Date of completion - 5.7.2021					
Actual date of completion - 29.1.2022					
① Restoration of faucils					
— do — do — all complete					
26m x 0.60m x 0.30m = 4.68m ³					
10m x 0.60m x 0.30m = 1.80m ³					
11m x 0.60m x 0.30m = 1.98m ³					
18m x 0.60m x 0.30m = 3.24m ³					
21m x 0.60m x 0.30m = 3.78m ³					
11.9m x 0.80m x 0.30m = 2.86m ³					
27.5m x 0.80m x 0.30m = 6.60m ³					
11.18m x 0.80m x 0.30m = 2.68m ³					
5m x 1.00m x 0.30m = 1.50m ³					
16m x 1.00m x 0.30m = 4.80m ³					
11m x 1.00m x 0.30m = 3.30m ³					
13.30m x 0.50m x 0.30m = 1.99m ³					
7m x 0.50m x 0.30m = 1.05m ³					
8m x 0.60m x 0.30m = 1.44m ³					
9m x 0.60m x 0.30m = 1.62m ³					
11m x 0.70m x 0.30m = 2.31m ³					
7m x 0.80m x 0.30m = 1.68m ³					
Continuation					47.31m ³

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
① restoration of fair cuts					
Qty = 131.47 m ² wide					
TMB P 68-69					
@ Rs 380.58/m ²					Rs 50036.00
② maintenance of earthen shoulder					
Qty = ^{677.27} 499.92 m ² wide					
TMB P 70-71					
@ Rs 58.37/m ²					Rs 29
					Rs 39532.00
③ repair of pot holes filled with 75 mm BM X 1-25					
Qty = 8.46 m ² wide					
TMB P 71					
@ Rs 11307.80/m ²					Rs 95708.00
④ patch repair over pot holes with mix seal surfacing					
Qty = 112.85 m ² wide					
TMB P 72					
@ Rs 293.05/m ²					Rs 33071.00
⑤ maintenance of earthen drains					

Continuation

