

Abstract for Cost

① Restoration of surface etc

Qty : 73.28 m³ from TM BP-52

@ 380.58 ————— Rs 27889.00

② making up shoulder etc

Qty : 631.50 m² from TM BP-52

@ 58.37 ————— Rs 36861.00

③ Repair of pot holes filled with

75 mm WBM etc

Qty - 84.84 m³ from TM BP-52

@ 344.13 ————— Rs 29196.00

④ Patch repairs over BT surface etc

Qty - 84.84 m² from TM BP-52

@ 233.00 ————— Rs 20277.00

Continuation

Sch. XLV-Form No. 134 ⁵⁴

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
⑤ maintenance of HP culvert etc					
Qty - 6.00 NO from TMRP-53					
@ 1117.00				RS	6702.00
⑥ maintenance of road sign etc					
Qty - 0.21 KM from TMRP-53					
@ 1074.510				RS	226.00
⑦ maintenance of 200 M ² KM stone					
Qty - 0.25 KM from TMRP-53					
@ 573.96				RS	143.00
⑧ cutting of branches and of forest					
Qty - 2.00 NO from TMRP-53					
@ 106.52				RS	213.00
					121507.00
less 10% (G)					12151.00

109356.00

Say 109,356/-

@ Recd
18/10/24
JE

material statement

① Earth: -	168.00 m ³
② stone chips: -	4.58 m ³
③ S-90: -	1.61 m ³
	@ Recd 18/10/24 JE

Continuation