INSPECTION REPORT FOR MOTORABLE WORK				
Date:- 98 111124				
1 Name of PIUs:-	Priyaranjan Das (Executive Engineer Saharsa)			
Name of Block/Road :-	RCC Bridg	e over	Parsal	ha Dhan to Near
2	RCC Bridge over parsala Dhan to Near Ram pokher west in Sahuriya panchage			
A. For Road				
1 Damage Location/Chainage :- N	J/A			
2 Damage Length:- N/A mt.				
3 Nature of damage (i) Breach :- N/A				
(Length Wise):-	(ii) Crust Diamage :- N/A			
	(iii) Only Flank Diamage:- N/A			
Whether traffic fully/Partialiy obstructed:- Fully obstructed				
4 Details of Restoration Works :-				
i Material being used in Restor			N/A	
ii Equipments/Tools being used in		N/A		
iii Restored Length:-		In open Area:-		N/A mt.
		In Habitation	Area:-	N/A mt.
IV II Restoration work done in Totalion Their Co.				
B. For Bridge				
			. 0	
1 Damage Location/Chainage:- A 1 Side Approach & A2 Side Approach 2 Damage Length:- 129.W M 3 Nature of damage:- Approach round web badly damaged				
2 Damage Length:- 129.W M				
3 Nature of damage: Approach rond wes badly danaged				
4 Details of Restoration Works: - Brice bat filling				
i Material being used in Restortion works:- Back Back				
ii Equipments/Tools being used in Restoration works:- Tre ctor JCB Machine				
ii Procedure taken up in Restoration works:- Approach Mad Maintained				
v Restored Length:-	29.W			mt.
verall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory				
O &				
11124				
Signature of Inspection(Office (Name of inspector)				
				Rural Worl spartment
				Warks Division, Saharsa