

Cont of Road From Milki Pmhsy Road to
Muraitna South tola in Jale Block

Schedule XLV-Form No. 134
Pmhsy (Sc)

R. V. D. (M) Division
DIVISION

DATE 13/5/2019

JALE
SUB-DIVISION

Ag. No: 13/5RD/2019-20

MEASUREMENT BOOK

K. D. Construction. No. 838

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF COST				
1.	Restoration of rain cists/ Berms in soil all comp.				
	vide TMS p. No- 36-37				
	qt- ① 85.15 m ³				
	08395-45/m ³ — 33673.00				
2.	Making up of shoulder/ Berms with all comp.				
	vide TMS p. No- 37				
	qt- ② 484.31 m ²				
	0854-16/m ² — 26230.00				
3.	Repair of pot holes with all comp.				
	vide TMS p. No- 37-38				
	qt- ③ 4.01 m ³				
	0810469.00/m ³ — 41981.00				
4.	Patch repair over pot holes 20mm thick all comp.				
	vide TMS p. No- 38				
	qt- ④ 53.46 m ²				
	08222.85/m ² — 11909.00				

Continuation

6-713793.00

Continuation