

नवाड

11/12/2019

Work done in year 2019-2020
Bara panchay Road to Chikara Bigha
Masaurhi Panpan River - 10K

Schedule XLV-Form No. 134

बोला नरारी वारा पमपस रोड से छपन बिहार मुतहरी
पुनपुन नदी तट पथ निर्माण
Pali ghat

DIVISION

Sub-division - Sub-division Kumar

SUB-DIVISION

Measurement Book

508

Sub-division - Sub-division Kumar

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Rectification of drainage/					
Berms with soil reinforcement - 8/8					
8x	9.50	0.400	0.400	=	12.16m ³
19x	11.70	0.750	0.400	=	66.69m ³
14x	10.60	0.450	0.250	=	16.65m ³
5x	12.70	0.300	0.300	=	5.71m ³
6x	11.60	0.400	0.200	=	5.57m ³
5x	10.70	0.300	0.300	=	8.02m ³
6x	12.50	0.450	0.200	=	7.42m ³
5x	11.70	0.350	0.400	=	8.19m ³
4x	12.60	0.650	0.300	=	9.82m ³
5x	11.50	0.750	0.400	=	17.25m ³
5x	12.00	0.900	0.300	=	19.14m ³
5x	10.00	0.650	0.200	=	6.50m ³
6x	6.80	0.800	0.200	=	6.528m ³
					189.84m ³
② Making up of Berms/Shoulder,					
stripping excess soil - 8/8					
6x	16.50	1.00		=	97.80m ³
10x	17.60	0.750		=	132.00m ³
7x	16.50	0.900		=	103.95m ³
13x	10.10	0.700		=	91.91m ³
14x	12.40	0.900		=	156.24m ³
8x	19.0	0.750		=	114.00m ³
12x	16.50	0.900		=	178.20m ³

Continuation

Contents	Details of actual measurement				Particulars
	D.	B.	L.	No.	
					15x11.40x0.320 = 85.52m ³
					4x15.35x0.970 = 59.57m ³
					6x6.50x0.860 = 31.20m ³
					10.50.37m
					⑤ patch repair over bitu- menous surface with 28.0mm cement concrete
					13.0x4.50x1.10 = 64.346m ³
					16.0x2.85x1.20 = 54.720m ³
					9.0x3.25x1.10 = 32.173m ³
					11.0x2.15x0.95 = 22.466m ³
					15.0x4.0x1.05 = 63.753m ³
					237.48m ³
					⑥ patch repair over bitu- menous surface with 28.0mm cement concrete
					13.0x4.50x1.10 = 64.346m ³
					16.0x2.85x1.20 = 54.720m ³
					9.0x3.25x1.10 = 32.173m ³
					11.0x2.15x0.95 = 22.466m ³
					15.0x4.0x1.05 = 63.753m ³
					17.753m ³

Continuation

ABSTRACT OF COST

X-84

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(15.1) Restoration of worn cuts/berris - - - - -				0/5	
Qty vid TMB P - (88)					
189.84 m ³ @ RS 352.75 = RS 66366.0					
(15.2) Making up of berris/shoulder, stripping excess soil - - - - -				0/1	
Qty vid TMB P - (84)					
1050.37 m ² @ RS 52.64 = RS 55291.0					
(15.3) Repair of pot holes					
Filled with 75mm - - - - -				0/1	
Qty vid TMB P - (89)					
17.75 m ³ @ RS 827.47 = RS 14691.70					
(15.3ii) Patch repair over pot-holes with 20mm - - - - -				0/1	
Qty vid TMB P - (89)					
237.438 m ² @ RS 266.76 = RS 63339.0					
(15.3iii) Patch repair over bituminous surface with 20mm premix Carpet - - - - -				0/1	
Qty vid TMB P - (90)					
237.438 m ² @ RS 280.03 = RS 66490.0					
(15.7ii) Maintenance of G.O. road					
(17PC) - - - - -				0/1	
Qty vid TMB P - (90)					
1.0 m ³ @ RS 1082.90 = RS 1083.00					

[illegible]