

NABARD

Gram Chetki Singh wahni mukhya sadak

Shambhu Singh ka Ghar To Rannir Singh Gm Hota

Executive Engineer

R.W.D. & Irrigation

Mr Bhagwanpur mukhya Sadak

DIVISION

FINAL

14/7/14

SUB-DIVISION

Measurement Book

Measurement

2444

Si Parnal Ranjan

Sch. XLV-Form No. 134

Sch. XLV-Form No. 134					
Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year Maintenance work					
N/W:- Gromichhati Singhwadi ni Mukhya Sadak					
Shamchu Singh keghar to Ranvir Singh ke					
ghar hote hue Bhaywanpur Mukhya Sadak Tak					
Agency:- Sri Perimal Rangan.					
Ag. No:- F2-12/2018-19					
Maintenance Period:-					
Measurement					
D Rectification of Raincuts					
$12 \times 3.80 \times 0.80 \times 0.30 =$					10.94 m ³
$10 \times 5.30 \times 0.90 \times 0.30 =$					14.31 "
$18 \times 4.80 \times 0.70 \times 0.30 =$					18.14 "
$16 \times 5.80 \times 0.90 \times 0.30 =$					25.05 "
$14 \times 2.80 \times 0.80 \times 0.30 =$					9.41 "
					= 77.85 m ³
D Making up Berm & Shoulder					
$8 \times 4.30 \times 0.90 =$					30.96 m ²
$10 \times 5.60 \times 0.80 =$					44.80 "
$14 \times 5.10 \times 0.90 =$					64.26 "
$16 \times 3.90 \times 0.90 =$					56.16 "
					= 196.18 m ²
D Repair to pot holes filled with M.S.S.					
$6 \times 1.90 \times 1.20 =$					13.68 m ²
$8 \times 1.40 \times 1.40 =$					15.68 "
$4 \times 1.45 \times 1.0 =$					5.80 "
					= 35.16 m ²
D Patch Repair over B.T. Surface					
$4 \times 3.20 \times 1.50 =$					19.20 m ²

Continuation

[illegible]

Continuation