

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of Cost					
(1/59) Restoration of Raincuts ———— 2/2					
Qty vide TMB P-9					
Item No. (1)					
i.e. = 263.209 m ²					
(a) 412.71/m ² Rs. 108629=					
(2/60) making up of Berms/Shoulder Stopping ———— 2/2					
Qty vide TMB P-10					
Item No. (2)					
i.e. = 1462.00 m ²					
(a) 57.14/m ² Rs. 83539=					
(3/61) Repair of Pot holes with 75mm ———— 2/2					
Qty vide TMB P-10					
item No. (3) i.e. = 15.743 m ²					
(a) 10882.29/m ² Rs. 17320=					
(4/62) Patch Repair over Potholes ———— 2/2					
Qty vide TMB P-10					
Item No. (4)					
i.e. = 210.00 m ²					
(a) 264.42/m ² Rs. 55486=					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5/64) maintenance of					
CD Works					
Qty vide TMB P-11					
Item No. (6)					
i.e. = 3.0 Nos					
② 1109.67/Each					Rs 9329=
(6/65) maintenance of					
Road signs					
Qty vide TMB P-11					
Item No. (7)					
i.e. = 3.050 Km					
② 1055.94/Km					Rs 3221=
(7/66) maintenance of					
200m, Km Stone					
Qty vide TMB P-11					
Item No. (8)					
i.e. = 3.050 Km					
② 675.98/Km					Rs 9062=
(8/67) Cutting of branches					
of trees					
Qty vide TMB P-11					
Item No. (9)					
i.e. = 5 Nos					
② 115.94/Each					Rs 580=

[illegible]