

Home of Work: R-E. Pich Sakak TB Dhamak Taly

Lamar Tal

Mmuy (SC) (2017-18)

Schedule XLV-Form No. 134

YAES 19/09/21

Agency - Artisan Cons.

DIVISION

MB No. - 437

SUB-DIVISION

Measurement Book

4th
11/8/24
S.E

① Restoration of Raincuts with
Soil.

Qty	vide TMB P-60	item-No-1
i.e	96.660 m ³	

(9) $378.32 / m^3 = 36568.0$

② making up loss of material on shoulder to the design level

Oty	vide TMB P-60	cifem NO. 2
i.e	180.00 m ²	

② $57.35 / m^2 = 10323.00$

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ Repair of pot holes by remove of failed material.					
Qty vide TMB P-⑥① item No-③					
i.e 37.555 m ²					
④ 301.21 / m ²					= 11312.00
④ maintenance of WBM Road					
Qty vide TMB P-⑥① item No-③					
i.e 37.555 m ²					
④ 434.70 m ²					= 16325.00
⑤ patch repair on already filled pot holes.					
Qty vide TMB P-⑥① item No-⑤					
i.e 37.555 m ²					
④ 285.87 / m ²					= 10725.00
⑥ maintenance of CD work					
Qty vide TMB P-⑥① item No-⑥					
i.e 1 No's					
④ 1109.67 / No's					= 1110.00
⑦ maintenance of Road sign					
Qty vide TMB P-⑥① item No-⑦					
i.e 1.202 km					
④ 1066.51 / km					= 1282.00
⑧ maintenance of 200m x km Stone.					
Qty vide TMB P-⑥① item No-⑧					
i.e 0.216 km					
④ 725.9 / km					= 157.00

Continuation

Continuation