

ABSTRACT OF COST

1. Restoration of talab Cuts

With Soil on maximum Quantity

vide Page (42) - 121.14 m³

@ RS. 380.58/m³ RS. 46104.52

2. Making up of Berms/Shoulder

Shooting on Soil Quantity vide Page (42)
- 539.40 m³ @ RS. 58.37/m³ RS. 31485.58

Continuation

RS. 197589.10

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					RS-975892
3. Patch repairs over pot holes with 2mm mpa Seal					
Surface. Quantity of Seal					
-(43). 97.60m ² .					
@ RS. 285.90/m ²					RS-279042
4. Maintenance of Pot holes					
mpa Seal Surface of Road					
Quantity of Seal - (43)					
97.60m ² @ RS. 304.76/m ²					RS-297452
5. Maintenance of Kurr Pipe					
Cutting and CD Hole					
Quantity of Pipe - (43) 3 No.					
@ RS. 1117.0 each					RS-33512
6. Maintenance of Road					
Gravel width (43).					
0.24 KM @ RS. 1074.51/m ²					RS-25822
7. Maintenance of Road and					
KM Stone width (43).					
0.30 KM @ RS. 651.44/m ²					RS-19520
8. Cutting of Branches of tree and Shrub					
Quantity - (43) 3 No.					
@ RS. 106.52 each					RS-3202
					RS-1593622

Continuation

P.T.O.