

~~MAJGASY NEN.SIC~~

MA.B.NO-3232

पुनर्मापन कार्य २५/३/१९९९ तक ५५ /
पुनर्मापन कार्य - ५५ / ५०३० / २०१९-२०

Measurement Book

Schedule XLV-Form No. 134

पुनर्मापन कार्य २५/३/१९९९ तक
पुनर्मापन कार्य २५/३/१९९९ तक
पुनर्मापन कार्य २५/३/१९९९ तक

DIVISION

SUB-DIVISION

MA.B.NO-3232

2nd year Maintenance Bill

46

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w:	M/O Road from Kurnaa Sachapur				
	Path to Annual tank under				
	NNHSY-52.				
Agency:	Sh. Rajeev Kumar Singh				
Amt No:	45/SBD/2019-20.				
D.O.C(amt) :	10-12-2021				
	<u>Road entries</u>				
(1)	Restoration of Rainfall - -				
	$10 \times 2.50 \times 1.50 \times 0.30 =$				11.25
	$6 \times 3.00 \times 1.70 \times 0.30 =$				8.10
	$8 \times 2.75 \times 1.25 \times 0.30 =$				8.25
	$12 \times 2.00 \times 1.50 \times 0.30 =$				10.80
	$10 \times 2.10 \times 1.25 \times 0.30 =$				11.62
	$6 \times 2.25 \times 1.75 \times 0.30 =$				7.09
	$12 \times 3.00 \times 1.75 \times 0.30 =$				18.90
	$10 \times 2.10 \times .50 \times 0.30 =$				9.45
	TOTAL =				85.46m ³
(2)	Making up of Berms & shoulders - -				
	$10 \times 5.25 \times 1.125 =$				59.06
	$12 \times 4.75 \times 1.125 =$				64.12
	$10 \times 5.00 \times 1.125 =$				56.25
	$14 \times 4.50 \times 1.125 =$				70.87
	$5 \times 4.90 \times 1.125 =$				27.56
	TOTAL :				277.86m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) Patching up over Bitu--					
		5 x 1.50 x 1.00			= 7.50
		4 x 3.00 x 0.75			= 6.00
		6 x 1.25 x 1.25			= 9.37
		5 x 2.00 x 0.50			= 5.00
		6 x 1.50 x 0.75			= 6.75
		1 x 3.00 x 1.00			= 3.50
					T. Qty = 38.12m ²
(9) Maintenance of Road Sign -					
		0.17 x 1			= 0.17km
(10) Maintenance of 200m x 2 km					
		0.21 x 1			= 0.21km
(11) Cutting of Branch of tree -					
		2 x 1.00			= 2.00
(ii) Cutting of shrubs -					
		9 x 1.00			= 9.00
(iii) Trimming of grassland -					
		2 x 7.00 x 1.50			= 21.00m ²
P. Singh 14/8/24 T.S.					
P. Singh 14/8/24 A.E.					
Abstract of cost:					
(1) Restoration of Raincut -					
	TMB P-46	85.46 @	378.32		= 32331.00
					/

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
② Mowing up by Berms/shoulder					
TMB/ P-46	277.86	@	57.14		= 15877 = 0
⑤ Patch repair over Bitum.					
TMB/ P-47	38.12	@	326.51		= 12447 = 0
⑨ M/o Road Slab ---					
TMB/ P-47	0.17	@	1066.50		= 182 = 0
⑩ M/o 200m & Km Stone --					
TMB/ P-47	0.21	@	641.62		= 135 = 0
11.(i) Cutting of Branch after					
TMB/ P-47	2.00	@	105.39		= 211 = 0
(ii) Cutting of shrubs ---					
TMB/ P-47	9.00	@	6.47		= 58 = 0
(iii) Trimming of grass/wood --					
TMB/ P-47	21.00	@	2.16		= 45 = 0
Total Rs.					61285 = 0
less 10% below (-) Rs.					6128 = 0
Grand Rs.					55157 = 0
Prepared by 11/09/24 I.S. Checked by 11/09/24 A.S. all 14/08/24 E.S.					
Materials listed					
(i) E/c: 128.00 m ³					
(ii) Stone chips: 1.04 m ³					
(iii) Emulsion P.S. = 0.012 MT					
(iv) Bitum Va-10 = 0.073 MT					
Prepared by 10/09/24 I.S. Checked by 10/09/24 A.S.					