

5 yrs	Maintenance Work			
4th	yr	Maintenance	Pool	
N/Road 1- 5 yrs Routine Maintenance of				
Road from Jamsi Lachhwar				
PWD Rd near Mark to Sabalhigha				
Road				
Agency 1- MD Shahbaz Afroz				
At- Purnani Bazar Jamsi				
Ag NO 1-	01/	SAD/	2018	-19
D.O.C	11.	04-	2018	
D.O. Completion 10. 4. 2019				
Actual Date of Completion - 25.10.20				
Date of entry				
Maintenance Cost Rs 20 3386 = 10				

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of Ravines					
Banks with Soil masonry					
6 x 15.0 x 1.20 x 0.30 =					32.40 M ³
8 x 19.0 x 0.90 x 0.30 =					41.04 M ³
10 x 12.0 x 0.75 x 0.30 =					27.00 M ³
15 x 18.0 x 0.60 x 0.30 =					48.60 M ³
12 x 23.0 x 0.45 x 0.30 =					37.26 M ³
7 x 14.0 x 1.20 x 0.30 =					35.28 M ³
					221.58 M ³
2. Making up of Banks					
Shoulder sloping down					
Soil from the Shoulder surface to achieved level					
12 x 30.0 x 1.20 =					432.00 M ²
18 x 12.0 x 0.90 =					194.40 M ²
08 x 19.0 x 0.60 =					97.20 M ²
					717.60 M ²
3. Repair of Pot holes					
filled with 75 mm WBM					
1.25					
08 x 11.0 x 0.30 =					26.40 M ²
10 x 9.0 x 0.15 =					13.50 M ²
12 x 6.0 x 0.30 =					21.60 M ²
10 x 13.0 x 0.45 =					58.50 M ²
18 x 9.0 x 0.30 =					48.60 M ²
					168.60 M ²

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4 ii) Patch repairs over Pot-holes with 20 mm Premium Surfacing material.					
48 x 11.0 x 0.30			26.40	M ²	
10 x 9.0 x 0.15			13.50	M ²	
12 x 6.0 x 0.30			21.60	M ²	
10 x 13.0 x 0.45			58.50	M ²	
18 x 9.0 x 0.30			48.60	M ²	
			168.60	M ²	
5/7 Manti At H.P Culvert					
			6 Nos		

6/9 Manti At Road side					
			0.465	KM	
7/10 Manti At 200 M 1 KM Stone					
			0.55	KM	
8/11 Cutting of branches of Trees					
			4 No		
9/11 Cutting of Shrubs from Roadways					
			18 No		
10/12 White-washing of Parapet walls of CD Work & Tree Trunks					

Continuation

475	4x Mounts	Rs 11	
ABSTRACTS OF COST			
Restoration of Rainfall			
Qty	Rate	in Rs	
		221.58	M ²
348247	1/14		Rs 77213
Making up of Boulders			
Shoulder striping excise			
Soil from the Shoulder			
Surface to achieve level			
Qty	Rate	in Rs	
		717.60	M ²
51240	1/14		Rs 36885
		Rs 114	0982

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B 17 B 114 098		
3. Repair of Path hole filled with 25 mm WBM & 25					
Qty vide P No 22 in TM 2			168.60 M ²		
@ B 1972 = 67/M ²				B 33 327 =	
4 Patch repair over path hole with 20 mm concrete Surfacing materials					
Qty vide P No 22 in TM 3			168.60 M ²		
@ B 268 = 28/M ²				B 45232 =	
5 Maults of H. Pavement					
Qty vide P No 22 in TM B			06 MS		
@ B 1098 = 11/cd				B 6589 =	
6 Maults of Road Sides					
Qty vide P No 22 in TM D			0.465 KM		
@ B 1054 = 98/KM				B 491 =	
7 Maults of 240 M x 2 KM					
Stone					
Qty vide P No 22 in TM B			0.55 KM		
@ B 567 = 15/KM				B 312 =	
			Total B	200	04920

Continuation

Sch. XLV-Form No. 134

[illegible]