

1st year maintenance

26

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
New: Maintenance of Road from					
Rameshwar Mahato (Saree) ka Dukan					
TO Hapur mahato ke ghar (Sari).					
Agency. Ravi prakash Singh.					
Agri No - 69 (S.B.D) / 2020-21					
D.O. No - 04.02.2021					
D.O. C - 03.11.2021					
Actual p.o.c - 21.07.2022					
① Restoration of Rainwater —					
$6 \times 4.10 \times 1.10 \times 0.25 = 6.61$					
$4 \times 3.15 \times 1.10 \times 0.30 = 4.16$					
$9 \times 2.50 \times 0.95 \times 0.25 = 7.48$					
$8 \times 3.70 \times 0.90 \times 0.30 = 7.99$					
$5 \times 2.50 \times 1.10 \times 0.25 = 4.23$					

32.61 m³

② Making up of Bitum —

L.H.S.	$20 \times 8.10 \times 0.75$	120.00
R.H.S.	$17 \times 10.10 \times 0.80$	136.10
		256.10 m ²

③ Patch repair with M.U. —

	$4 \times 1.10 \times 0.90$	3.96
	$6 \times 1.55 \times 1.10$	10.23
		14.19 m ²

④ Maint. of Home pipe outlet —

2 x 1 = 2.00 m²

~~⑤~~

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of Cost</u>					
① Rectification of Room Cuts -					
Qty wire THB R (26)					
L- 27.84 m ³ @ R 394.20 / m ³ — R					10978 =
② Making up of Below -					
Qty wire THB R (26)					
L- 255.94 m ² @ R 58.97 / m ² — R					15093 =
③ Patch repair with HSB -					
Qty wire THB R (26)					
L- 12.89 m ² @ R 228.36 / m ² — R					2905 =
④ Guard. of Home pipe outlet -					
Qty wire THB R (26)					
2.00 Nos @ R 1130.67 / each — R					2261 =

					R. 31234=
Acry. GSI + L-accy (13 1/2) — R					4060=
Acry. S. Fee — R					242=
					R 35536=
lay 12.55 t. — R					4460=
					R 39996=

Qty. - 66.231 m³Sch. 1. - 0.248 m³