

5th year maintenance
43

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w:- Maint. of Road from Kusaiya Pasunath thoker ke gher to Main pacher bridge side ke gher hok huc Bisher Asthan 702 tax.					
Agency - Mcl. mutafa.					
App. No - 25 (SBD) / 2018-2019					
D.O. No - 04.05.2018					
Actual D.O.C - 01.02.2019					
① Restoration of Rain cuts -					
	25	1.85	0.95	0.35	15.38
	40	1.55	1.10	0.30	20.46
	30	1.70	0.75	0.35	13.39
	22	2.15	1.20	0.35	19.67
	23	2.35	0.90	0.30	17.13
	26	1.90	0.85	0.35	14.69
					100.92 m ³
② Maintenance of earthen Shoulder					
	15	25.00	0.75		281.25
	12	15.00	0.85		153.00
	14	12.00	0.90		151.20
					585.45
③ Repair to pot holes by removal of failed material -					
	4	4.00	1.40		22.40
					22.28

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
② Maintenance of earthen sh...					
Qty with THB R (43)					
L- 536.63 m ² @ R 56.01/m ² R 30057 =					
③ Repair to pot holes —					
Qty with THB R (43)					
L- 48.04 m ² @ R 240.56/m ² R 11556 =					
④ The maint. of WBM —					
Qty with THB R (44)					
L- 48.04 m ² @ R 240.56/m ² R 11556 =					
⑤ Patch repair on already killed top —					
Qty with THB R (44)					
L- 48.04 m ² @ R 263.19/m ² R 12644 =					

⑥ Tarmacadam of gravel —

Qty with THB R (44)

1380.00 m² @ R 2.14/m² R 2953 =

R 104772 =

lay 10 cm Below — R 10477 =

R 94295 =



Hale

Qty- 177.08 m³S/cuts- 2.594 m³