

Dhamsoi Denaathapur road to

Kazrahanxi Harigan tola

Schedule XLV-Form No. 134

mmbsy (5c)

Buxar

DIVISION

J-taxhi

SUB-DIVISION

महाराष्ट्र राज्य सरकार

Measurement Book

135

18-14

5th & final year maintenance

67

Sch. XLV-Form No. 134

[illegible]

c) Restoration of main ch
with soil mounds - do -

$2 \times 30 \times 1.125 \times 0.3m = 60.75 m^3$	
$2 \times 2 \times 30 \times 1.15 \times 0.3m = 41.40 m^3$	
$2 \times 30 \times 1.125 \times 0.3m = 60.75 m^3$	
Total $\phi 4 = 162.90 m^3$	

27	Making up loss of material			
	irregular on shoulder etc			
	2 x 7 x 80 x 1.125 =	472.50	m ²	
	2 x 5 x 90 x 1.125 =	337.50	m ²	
	2 x 2 x 90 x 0.95 =	108.00	m ²	
	Total Qty	918.00	m ²	

③ Repair of pot holes filled with
75 mm WBM $\times 1.35$ — do —
 $9 \times 2.30 \times 1.50 = 31.05 \text{ m}^2$

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
10/14) B.F. -				75 -	222566 cu
Trimmed of grass					
went down the shoulder					
vide 11/85. p				pot - 68	
@ 2.08 / m				75 -	3089 20
11/15) white washing two racks					
on parapet walls - w -					
vide 11/85. p				pot - 69	
@ 19.89 / m				12 -	537.00
				12 -	226192 20
Less 10% below E				12 -	22619 20
				12 -	203573 20

[Signature]
76

Continuation