

MMG 5Y-Lo35 to Dreamer via.
(Gen) Deitrapur, (104.6460)

Schedule XLV-Form No. 134.

Ag No-47580/19-20

133.29718

1000

Rod (w) allu. Shergaon DIVISION

Mohapur

SUB-DIVISION

Agency Shergaon 1000

Measurement Book

Ag No-1141

1141

18.10.19

to

17-10-2020

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd year Maintenance					
Name of Work:- Const. of Road					
from 1035 to Dhamna					
via Baignathpur.					
Agency:- Srikant Kumar					
Agreement No:- 47/SBD/2019-20					
D.O.G. - 18.10.2019.					
D.O.C. - 17.10.2020					
Actual D.O.C. - 15.10.2020.					
Date of Measurement - 12/10/22					
1. Restoration of rain cuts/					
Beams with soil					
10 x 1.00 x 0.90 x 0.30 = 2.70 m ³					
9 x 1.50 x 1.00 x 0.30 = 4.05 m ³					
17 x 2.60 x 1.05 x 0.30 = 13.92 m ³					
21 x 4.00 x 0.95 x 0.30 = 23.94 m ³					
27 x 3.00 x 1.00 x 0.30 = 24.30 m ³					
20 x 5.00 x 0.90 x 0.30 = 27.00 m ³					
33 x 1.75 x 1.00 x 0.30 = 17.33 m ³					
113.24 m ³					
2. Making up of Berms/shoulders					
stripping excess soil from					
shoulder surface					
17 x 4.00 x 1.00 = 68.00 m ²					
11 x 3.00 x 1.00 = 33.00 m ²					
27 x 5.00 x 1.10 = 148.50 m ²					

Continuation

Material Statement -

1. Soil - 179.264 m^3 .
2. Stone Aggregate - 5.313 m^3
3. Bitumen Emulsion SS-1 = 3.12 kg .
4. Bitumen Emulsion RS-1 = 48.32 kg .
5. Bitumen S-50 = 368.03 kg .

At
12/10/22
S.E.

Scanned with CamScanner

ch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost.					
1/1 Restoration of ruins cut/					
Berms with soil:					
Qty. Vol. TMB item					
101 PMSI = 113.24 m ³					
CM 380 = 58/m ² - 443097 =					
2/2 Making up of Berms/					
Shoulders -					
Qty. Vol. TMB PMSI					
Item 102 = 628.59 m ²					
CM 58 = 37/m ² - 36708 =					
3/3 Repair of pot holes.					
Qty. Vol. TMB item					
103 PMSI = 0.26 m ³					
CM 11272 = 15/m ³ - 2931 =					
4/4 Patch repair over pot					
holes -					
Qty. Vol. TMB item					
104 PMSI = 87.43 m ²					
CM 307 = 91/m ² - 26842 =					
5/5 Patch repair over the					
bituminous surface.					
Qty. Vol. TMB item					
105 PMSI = 87.34 m ²					
CM 311 = 13/m ² - 27174 =					
C/O - 1136752 =					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B/F		131.367522
6/6 Filling of cracks & joints					
Qty. waste TMB item					
NO 6 PMS 121865.00 m					
Q 134 = 69/m					15874722
7/8 Repair of concrete pavement.					
Qty. waste TMB item					
NO 7 PMS 92 = 8.40 m ²					
Q 13307201/m ²					15957922
8/9 Repair of old joint sealant					
Qty. waste TMB item					
NO 8 PMS 2 = 168.75 m ²					
Q 123 = 45/m					10395722
9/11 Maintenance of drainage pipe culverts.					
Qty. waste TMB item					
NO 9 PMS 2 = 6 NOS.					
Q 1117 = 40 each					10670222
10/14 Maintenance of road signs.					
Qty. waste TMB item					
NO 10 PMS 2 = 2.04 Km.					
Q 131074251/Km					15219222
11/15 Maint. of 900m of km stone.					
Qty. waste TMB PMS 2					
2.04 Km. Q 13643 = 75 Km					1313222
Continuation					
C/O — 131,62,24222					

Sch. XLV-Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	

Continuation