

Plan of work - PWD Road Accts & Pettigas  
of Phachhi Road.  
Schedule XLV-Form No.-134/Mysy(S.C.)

New Works Divi. Discharge & Division  
No. 52

Hayeghatt

Sub-Division

# MEASUREMENT BOOK

3330

Md. Miskinsa

Particulars No.	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
<u>40th year Maintenance</u>						
<u>Name of work - PWD road Ayan</u>						
<u>To Pothiyar Gachhi</u>						
<u>Agency - M.I. Mustafa</u>						
<u>Agreement no - 0750D/2013-18 (MMG 677)</u>						
<u>Date of work completion - 10/01/2019</u>						
<u>Date of entry - 10/10/2022</u>						
<u>① Maintenance of road work</u>						
<u>(LTP.) cutout.</u>						
<u>By. 8.00 m</u>						
<u>② White worked of parapet</u>						
<u>well</u>						
<u>By. 3x2.8 = 8.48 m</u>						
<u>③ Restoration of embank.</u>						
<u>Berm/ shoulder</u>						
<u>1 x 30.10 x 0.70 x 0.20 = 4.20 m<sup>3</sup></u>						
<u>1 x 25.00 x 0.60 x 0.20 = 3.00 m<sup>3</sup></u>						
<u>1 x 24.50 x 0.70 x 0.20 = 3.43 m<sup>3</sup></u>						
<u>1 x 18.60 x 0.70 x 0.30 = 3.90 m<sup>3</sup></u>						
<u>1 x 14.50 x 0.70 x 0.20 = 2.03 m<sup>3</sup></u>						
<u>1 x 5.60 x 0.90 x 0.20 = 1.25 m<sup>3</sup></u>						
<u>1 x 11.40 x 0.60 + 1.25 x 1.20 = 12.65 m<sup>3</sup></u>						
<u>1 x 6.80 x 0.60 + 1.10 x 1.20 = 5.44 m<sup>3</sup></u>						
<u>1 x 8.75 x 0.70 + 1.10 x 1.20 = 7.87 m<sup>3</sup></u>						
<u>1 x 14.50 x 0.60 + 1.10 x 1.20 = 11.60 m<sup>3</sup></u>						
<u>1 x 28.50 x 0.45 + 1.20 x 1.20 = 35.26 m<sup>3</sup></u>						
<u>1 x 27.50 x 0.60 + 1.40 x 1.50 = 40.80 m<sup>3</sup></u>						
<u>GO: 138.28 m<sup>3</sup></u>						

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

ABSTRACT OF COST.

(1) Restoration of road

Cut &amp; ready/ shoulder

By 158.44 m<sup>2</sup> — P/SI

(2) Making up of berms/ shoulder

shoulder &amp; top of recess

Soil

By 884.80 m<sup>2</sup> — P/SI@ 54.16 / m<sup>2</sup> — Rs 47921.20

(3) Repair of pot holes

fell → with bitumen

By 4.89 m<sup>2</sup> — P/SI@ 9625.65 / m<sup>2</sup> — Rs 47069.20

(4) patch repair over pot holes.

with 20 mm granular compact

with seal coat type 'B'

at cost

By 65.34 m<sup>2</sup> — P/SI@ 102.18 / m<sup>2</sup> — Rs 7062.20

(5) patch repair over bitumen

Surface with 20 mm granular

compact

By 65.13 m<sup>2</sup> — P/SI@ 97.38 / m<sup>2</sup> — Rs 6346.20

(6) Maintenance of C/D mode

(Hawk pipe cutting)

By 3.40 m<sup>2</sup> — P/SI@ 1067.85 / m<sup>2</sup> — Rs 3204.20

Co-Rs 108461.20

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B/F	—	Rs 56846/-
⑦ White washif of parapet well	—	—	—	—	
⑧ 63 m	—	—	—	—	
⑨ 15.55 m	—	—	—	—	Rs 980/-
⑩ Maintenance of 2000 ft	—	—	—	—	
By 1.92 km	—	—	—	—	P/52
⑪ 1025.95 km	—	—	—	—	Rs 2021/-
⑫ 200 m f	—	—	—	—	
km per	—	—	—	—	
By 1.92 km	—	—	—	—	P/52
⑬ 675.53 km	—	—	—	—	Rs 1134/-
					Rs 172,596/-
Less 10% as per Agreement	—	—	—	—	Rs 17260/-
					Rs 155336/-
					Guruji
					18/01/23
					AE