

L 056 to ~~Schedule~~ **Kha Bive** under **Munsy (SC)**
Form No. 134

Ag. No. 26 SBD/2029 - 2022 - 1.154 km

Sherghati

DIVISION

Dobhi

SUB-DIVISION

M/S K. V. R. INFRA TECH

Measurement Book

1367

1st Year Maintenance bill

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work	Construction of road				
	From L-56 To Jhalpura				
Agency-	M/s KVR Infralec				
Agreement No-	268130/21-22				
Item-①	Registration of Raincut				
	Berms with soil				
	= 0.				
Item-①	Repair of concrete				
	Pavement				
	$10 \times 0.45 \times 0.40 = 1.8 \text{ m}^2$				
	$15 \times 0.50 \times 0.45 = 3.375 \text{ m}^2$				
	$20 \times 0.50 \times 0.40 = 4.0 \text{ m}^2$				
	$15 \times 0.45 \times 0.35 = 2.3625 \text{ m}^2$				
	$16 \times 0.50 \times 0.35 = 2.80 \text{ m}^2$				
	$15 \times 0.60 \times 0.50 = 4.5 \text{ m}^2$				
	$18 \times 0.55 \times 0.45 = 4.45 \text{ m}^2$				
	$20 \times 0.50 \times 0.375 = 3.75 \text{ m}^2$				
	27.03 m^2				
Item-②	Repair of old joint				
	sealant				
	$260 \text{ ft} \times 3.75 = 975 \text{ m}$				
	$25 \text{ ft} \times 3.70 = 92.5 \text{ m}$				
	1067.5 m				
Item ③	Maintenance of H.P				
	culvert				
	310				

Continuation

[illegible]

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Cont of a
	No.	L.	B.	D.	
item <u>Abstract of Cost</u>					
(1/8/10107) Repair of concrete pavement					
V.T.M.B.P.H. - (38)					
item (1) - 27.03 m					
8 245.87/m ² — 6646=					
(2/9-Rep 10.10) Repair of old joint sealant					
V.T.M.B.P.H. - (38)					
item (2) - 1062.54					
8 23.49/m — 28076=					
(3/15-20) maintenance of H-P culvert					
V.T.M.B.P.H. - (38)					
item (3) - 3 m					
8 1130.67/m — 3392=					
(4/15-21) maintenance of slab culvert					
V.T.M.B.P.H. - (39)					
item (4) - 1 m					
8 2329.21/m — 2329=					
(5/15-9) maintenance of Road sign					
V.T.M.B.P.H. - (39)					
item (5) - 1.15 m					
8 1077.81/m — 1239=					

Continuation

Continuation