

Name of Work: - PMGSY Road to Banthi talu
Under PMGSY (SC)

Schedule XLV-Form No. 134

Name of Agency: - Chauray Tiliari

DIVISION

Baikunthpur

SUB-DIVISION

M.B.No-A.87

MEASUREMENT BOOK

Abstract of Cost		
①	Restoration of rain cuts with soil.	
	Qty. Vids TMBP. (53) Item no ①	
	1,2 - 14.48 m ³	
	(a) 379.59/m ²	₹ 5370.00
②	Making up of Berms/shoulder.	
	Qty. Vids TMBP. (53) Item no ②	
	1,2 - 207.09 m ²	
	(a) 57.01/m ²	₹ 11806.00
③	Repair of pot holes.	
	Qty. Vids TMBP. (54) Item no ③	
	1,2 - 15.63 m ²	
	(a) 492.27/m ²	₹ 7694.00
④	Patch repair over bituminous surface.	
	Qty. Vids TMBP. (54) Item no ④	

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1.1.1.1	15.63 m ²			
	(a)	294.63/m ²		2	4605.00
(5) Maintenance of road signs.					
Qty. Vid. TMBP (54) item no (5)					
1.1.1.1	0.298 km				
(a)	1054.28/km		2	314.00	
(6) Maintenance of 200m 2km stone.					
Qty. Vid. TMBP (54) item no (6)					
1.1.1.1	0.595 km				
(a)	688.17/km		2	409.00	
(7) Cutting of branches of trees & shrubs.					
Qty. Vid. TMBP (54) item no (7)					
1.1.1.1	1 no				
(a)	106.12/no		2	106.00	
(8) Cutting of shrubs from roadway.					
Qty. Vid. TMBP (54) item no (8)					
1.1.1.1	3 nos.				
(a)	6.51/no		2	20.00	
(9) Maintenance of trees by the road side					
Qty. Vid. TMBP (54) item no (9)					
1.1.1.1	22 nos.				
(a)	561.46/no		2	12352.00	
(10) Trimming of grass & weeds.					
Qty. Vid. TMBP (54) item no (10)					
1.1.1.1	224.385 m ²				
(a)	2.17 m ²		2	487.00	
			2	43163.00	

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			12/F	2	43163.00
Add		Gas. T @ 12.4	2		5180.00
		Lites @ 1.1	2		422.00
			2		48775.00
		Below @ 1.1	2		537.00
			2		48238.00

Grand

20.804
AT

Material statement

$$E/W = 41.67 \text{ m}^3$$

$$RSI = 5 \text{ kg}$$

$$S90 = 30 \text{ kg}$$

$$\text{stone chips} = 0.42 \text{ m}^3$$

$$\text{stone agg} = 1.41 \text{ m}^3$$

Continuation