

NHBARD

Name of Reel:- PMHSY Read to Simhasani Mandir
Girgi Tala

(17-18)

Schedule XLV-Form No. 134

Name of Agency:- Bindu Kumar Upadhyay

Bless N - Bank with pure

9308 87

DIVISION

SUB-DIVISION

M.B. No - 434

Measurement Book

3rd year Maintⁿ Bill.

48

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - PM/GSY					
Rd. to Sinhasini Mandir					
Giri-tola					
Agency - M/s Binod kr.					
Upadhyay					
Agree. No. -					
Date of Commencement -					
15-07-2019.					

① Restoration of raincuts

Berms -

3 x 8.15 x 1.10 x 0.20	-	5.38 m ³
1 x 9.25 x 1.55 x 0.25	-	3.55 m ³
3 x 8.05 x 0.70 x 0.25	-	4.23 m ³
5 x 9.00 x 0.90 x 0.30	-	12.15 m ³
6 x 5.50 x 1.05 x 0.20	-	6.93 m ³
2 x 10.00 x 1.50 x 0.25	-	7.50 m ³
5 x 3.55 x 1.55 x 0.30	-	8.25 m ³
4 x 7.05 x 1.65 x 0.20	-	9.31 m ³
9 x 4.50 x 1.50 x 0.25	-	15.19 m ³
		72.52 m ³

② Making up berms / shoulder stripping.

7 x 7.00 x 1.45	-	71.05 m ²
4 x 11.05 x 1.70	-	75.14 m ²
7 x 8.00 x 1.57	-	87.92 m ²
3 x 7.85 x 1.55	-	36.50 m ²

Continuation
5 x 9.00 x 1.60 - 76.40 m²
346.61 m²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(10) Trimming of grass & weeds					531.58 m ²
Suppl.					
2/01/24.					
J.B.					
Abstract of cost.					
(1/1) Restoration of ravine cut					
72.52 m ³ Qty vide TMBP (48)					
item (1) @ Rs. 365.24/m ³ - Rs. 26,487.20					
(2/2) Making up of Berans					
3460.61 m ² Qty vide TMBP (49)					
item (2) @ Rs. 54.16/m ² - Rs. 18,772.20					
(3/3) Repair of pot holes					
filled with 75 mm BM					
5.561 m ³ Qty vide TMBP (49)					
item (3) @ Rs. 11612.18/m ³ - Rs. 64,575.20					
(4/4) Patch repair over					
pot holes with 20 mm					
Premium Carpet					
74.147 m ² Qty vide TMBP (49)					
item (4) @ Rs. 219.35/m ² - Rs. 16,264.20					
(5/5) Patch repair over					
bituminous surface					
with Seal Coat					
74.147 m ² Qty vide TMBP (49)					
item (5) @ Rs. 311.87/m ² - Rs. 23,124.20					

Continuation

Continuation