

✓ U.A. vide Letter No.- 1086, dated- 1/3/2024
U.A. Length - 2.40 Km

U.A. Details:

Cost of initial rectification
with surface Renewal RS 125.2140 Lac
5 yrs. Maintenance RS 17.1440 Lac
Cost of emergent RS 12.52140 Lac
Total RS 154.87940 Lac

Estimate Cost:

Cost of Initial Rectification
With Surface Renewal- 125.097 Lac
Cost of 5yrs Maintenance- 17.144 Lac
142.241 Lac

T.O. No.- 101/23-24

Ref. SE Letter No- 864

dt- 2.4.24

dt- 21/03/24

Technically Sanctioned for Rs. 142.241 Lac

(Rupees One crore forty two lakh twenty
four thousand one hundred) only.

Technically sanction does not mean sanction
of rate instruction given in technical
should be followed strictly.

Chief Engineer-6

Darbhanga

Rural Works Department