

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, बेनीपुर

पत्रांक- 372

दिनांक- 8/4/25

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बेनीपुर ।

सेवा में,

नोडल पदाधिकारी,
3054 एम.आर. कोषांग,
ग्रामीण कार्य विभाग, बिहार, पटना ।

विषय- MR (3054) under New Maintenance Policy- 2018 के क्रियान्वित पथों के विपत्र भुगतान हेतु अधियाचना के संबंध में।

प्रसंग- भवदीय पत्रांक 113 अनु0 दिनांक 10.01.2020

महाषय,

उपर्युक्त विषयक प्रासंगिक पत्र के संबंध में कहना है कि कार्यप्रमण्डल बेनीपुर अन्तर्गत MR (3054) under New Maintenance Policy- 2018 के क्रियान्वित पथों में से कार्य पूर्ण कराये गये पथ के विपत्र भुगतान हेतु विहित प्रपत्र में अधियाचना तैयार कर आपके आवश्यक कार्यार्थ समर्पित की जाती है।

सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

अनु0- 1. अधियाचना विहित प्रपत्र में।

2. Recorder IRI की प्रतिहस्ताक्षरित प्रति।

विश्वासभाजन



कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल बेनीपुर


8/4/25


8/4/25

Form GFR 19- A
(See Government of India's Decision (I) below Rule - 150)
Form of Utilization Certificate upto the month 08.04.2025
New Maintenance Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs)	Amount Received (in lacs)	Particulars
1	New Maintenance Policy 2018	Letter No 56 Dated 12.08.2020 Letter No 86 Dated 11.12.2020	Rs 221.53629 Vide Letter No :- 29 Dated 30.03.2025	Certified that out of RS 2520.27196 lacs of grants in aid sanctioned during the Years up to 2024-25 in favour of Executive Engineer, RWD Works Division Benipur under this Department, a sum of Rs 2519.84266 lacs has been utilized for the purpose of New_MR Scheme remaining 0.42930 unutilized at the end of the period under report.
		Total :	221.53629	

Certified and verified myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised :-

- i Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii Construction material have been tested.
- iv Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- v All other codal formalities have been observed.

Physical Progress achieved :-

- i Construction of Road works.
- ii Construction of CD works


D.A.O.
RWD works Division
Benipur


Executive Engineer
RWD works Division
Benipur


A.P.
31/4/25

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : BENIPUR

Sl.No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percent age	Previous Total Allocated Amount (I Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against GST Claim (in lac)	Remarks
1	RM/DA/BEN/24/0002	Repair of RWD Road Ganoun to Adharpur	31909408001	1086 / 01.03.2024	1.500	91.3968	56.10685	8.11175	27 MBD/2024-25/ 08.10.20254	07.07.2025	04.02.2025	3495	25mm	5%	32.4182	32.4182	23.68183	Road Complete

Divisional Accounts Officer
RWD Works Division
BENIPUR

Executive Engineer
RWD Works Division
BENIPUR

Name of Road :- Repair of RWD Road Ganoun to Adharpur

Name of Customer :- JIMIDAR YADAV

Date	Time	Section	Length	Bumps	Speed	OR	CATEGORY	IRI	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	ROAD				
04/02/25	13:24:32	23	0.1	210	10.1	2100	G	3204	26.018754	86.307302	Normal
04/02/25	13:24:32	23	0.1	200	20.2	2000	G	3572	26.019677	86.308562	Normal
04/02/25	13:25:08	23	0.1	280	20.2	2800	G	2999	26.022867	86.307951	Normal
04/02/25	13:25:08	23	0.1	210	20.2	2100	G	3204	26.023426	86.307271	Curve
04/02/25	13:25:43	23	0.1	300	10.1	3000	G	3325	26.024059	86.305278	Culvert
04/02/25	13:26:18	23	0.1	250	10.1	2500	G	3658	26.024837	86.304247	Normal
04/02/25	13:26:18	23	0.1	200	10.1	2000	G	3890	26.02644	86.309077	Normal
04/02/25	13:27:00	23	0.1	140	10.1	1400	G	3409	26.026614	86.304712	Curve
04/02/25	13:27:29	23	0.1	170	10.1	1700	G	3450	26.030775	86.306755	Curve
04/02/25	13:28:00	23	0.1	170	10.1	1700	G	3750	26.025943	86.305503	Normal
04/02/25	13:28:40	23	0.1	190	10.1	1900	G	3933	26.023935	86.302413	Curve
04/02/25	13:28:40	23	0.1	230	20.2	2300	G	3431	26.025634	86.30274	Curve
04/02/25	13:28:39	23	0.1	210	10.1	2100	G	3204	26.025743	86.301395	Normal
04/02/25	13:29:14	23	0.1	150	10.1	1500	G	3533	26.025885	86.300489	Curve
04/02/25	13:29:14	23	0.1	180	10.1	1800	G	3863	26.026459	86.300643	Normal
								Average IRI		3495	

$$Y = 0 * X^2 + 1.136 * X - 181$$

$$X = 2700$$

$$Y = 2886$$


(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

Power
04/02/2025
J.E.

[Signature]
Executive Engineer
RWD Works Division
Benipur

File :D:\STECO-USB-GPS V1_1\18050845.Xls, Section No.:23, Eqn : $Y = 0 * X^2 + 1.136 * X - 181$
 Name of Customer :JIMIDAR YADAV, Name of Work/ Road :Ganoun To Aadharpur, Lab Job number :




Sam
 04/02/2005
 JC

E-E
 E-E Banipur
 Executive Engineer
 RWD Works Division
 Benipur

Test Date	Section	Road Name	Section To 450000	
March 1963	1223	Road Type	(R) RURAL ROAD	
Start S No		Side	Interval	
Start E No				
Weather		UV Range	1550 To 5500	mm/Km
Start Location		Dist Range	0 To 15	0 - 1000 m
End Location		Equation	7.9 - 0.02 - 1.135 - 0.001	

Map View

File D:\STECO-USO-GPS V1_1\110050045.xls, Section No. 23, Eqn. $Y = 0 \cdot X^2 + 1136 \cdot X - 101$



James J.E
04/22/2015

E.E. Benipuri
Executive Engineer
RWD Works Division
Benipur