

[illegible]

1				Restoration at grain culs			
do		do		all			
2	30.00 30.00	0.90 0.90	0.30 0.30	24.30			
4	25.00 25.00	0.90 0.90	0.30 0.30	27.00			
2	26.00 26.00	1.25 1.25	0.30 0.30	19.50			
6	30.00 30.00	0.90 0.90	0.30 0.30	48.60			
4	25.00 25.00	1.25 1.25	0.30 0.30	37.50			
2	16.00 16.00	1.25 1.25	0.30 0.30	12.00			
				168.90 m ³			
4	25.00 25.00	0.90 0.90	0.30 0.30	27.00			
				195.90 m ³			
2							
Making up to Berms!				Shoulder			
do		do		all			
2	25.00 25.00	1.00 1.00	50.00 m ²				
6	30.00 30.00	1.00 1.00	180.00 m ²				

Continuation

Abstract at cost

64

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of ruin culs					
do					all-
195.90 m ³	Page-59				item-①
₹ 386.14 / m ³					75645=w
② Making up of Berms/shoulder					
do					all-
1090 m ²	Page-60				item-②
₹ 57.36 / m ²					62522=w
③ Repair of Pot holes					
do					all-
195.41 m ²	Page-60				item-③
₹ 404.73 / m ²					79088=w
④ Patch repair over Pot holes					
do					all-
195.41 m ²	Page-61				item-④
₹ 289.49 / m ²					56569=w
⑤ Maintenance of Bitumen mix seal surfacing					do all-
195.41 m ²	Page-61				item-⑤
₹ 308.15 / m ²					60216=w
⑥ Maintenance of Hume pipe culvert					
do					all-
2 Nos	Page-61				Item-⑦
₹ 1130.67 / each					2261=w
⑦ Maintenance of slab-culvert					
do					all-
2 Nos	Page-62				item-⑧
₹ 2329.20 / Each					4658=w

Continuation

3,40959=w

[illegible]