

Piyaji North tola to Piyaji South tola

Shedule XLV Form No. 134. Rate — 005/18100

(1) IS+on A/C BILL — 3054900

Baysi

DIVISION

Baysa. (BRT)

SUB-DIVISION

Measurement Book

1339

Firoz Ahmad Khan.

62580 / 200-21 MMGYSC

1st years Maintenance Bill.

34

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No. •	L.	B.	D.	
N/W. Pivali North tola to					
Pivali South tola. under-					
MMWSY (S-1) in block - Baisa,					
Agency - Bro2 Ahmed Khan.					
At - Nisharganj, Near - Choti Masjid					
Line Bazar Purnea Bihari.					
Agreement No - 62 SBD/ 2020-21					
Date of Commencement - 22-09-2020					
Date of completion - 21-06-2021					
Record Entry					

- ① Restoration of Raincuts

Berms with Soil moorum

$$2 \times 9.00 \times 0.700 \times 0.300 = 3.78 \text{ M}^3$$

$$3 \times 7.00 \times 0.900 \times 0.300 = \underline{5.67 \text{ M}^3}$$

$$3 \times 6.50 \times 0.750 \times 0.300 = 4.38 \text{ m}^3$$

$$2 \times 8.30 \times 0.750 \times 0.250 = 8.11 \text{ ms}$$

$$= 16.94 \text{ m}^3$$

- ② Making up of Berner/shoulder

stripping excess soil from the

Shoulder Surface.

$$2 \times 7.00 \times 0.900 = 12.60 \text{ m}^2$$

$$2 \times 9.50 \times 0.850 = 16.15 \text{ m}^2$$

$$3 \times 4.90 \times 0.800 = 11.76 \text{ m}^3$$

$$5x \quad 6.50x \quad 0.900 \quad \underline{-29.25M^2}$$

Continuation

$$= 69.76 \text{ N}^2$$

Continuation