

62SBD / 2020-21 IMMGTYSL

Piyaji North tola to Piyaji South Tola

Schedule XLV Form No. 134. Rate — 0005/1600

(1) IS+on A/c Bill — 3054,900

Bayasi DIVISION

Bayasa. (अ०३११) SUB-DIVISION

Measurement Book

1939

Fird Ahmad Khan.

3rd Years maintenance Bill.

46

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NW - Piyasi North side to Piyasi South side,					
Agency - Laxmi Ahmed / Chandra					
AS. NO - G2SDD/2020-21					
D.O. A - 22-09-2020.					
D.O. C - 21-06-2021					
/					
Record Entry					
Restoration of Reimburse					
Benny with Soil Movement.					

Record Entry

① Restoration of Rainfed
Benches with Soil Mooring.

2 x 15.00 x 125 x 0.0002	2	11.25 m ³
--------------------------	---	----------------------

$$2 \times 12'10" \times 1'25" \times 0'300 = 9.10 \text{ m}^3$$

$$2 \times 4.50 \times 1.25 \times 0.300 = 3.37 \text{ m}^3$$

$$= 23.62 \text{ m}$$

② Making up of Bennis / should be stripping excess soil.

$$2 \times 20' \times 11'25'' = 50.00 \text{ M}^2$$

$$2415'00 \times 11.25 = 27150 M^2$$

$$2 \times 10^{-10} \text{ V} / \sqrt{25} = 25.00 \text{ Hz}$$

$$= 112.50 \text{ m}^2$$

③ Repetition of pot holes filled with 38 mm WBM.

$$3 \times 20.00 \times 2.50 \times 0.075 = 11.25 \text{ m}^3$$

$$4 \times 15 \times 10 \times 1.90 \times 0.025 = 8.55 \text{ m}^3$$

Continuation

$$\approx 19.80 \text{ m}^3$$

Continuation