

311210110

K.D

2nd Floor. 1st floor. 2nd floor.

S.C

Schedule XLV-Form No.-134

Agreement No - 3315310/2018-19 dt 7/6/18.

Agreement Value - 56414418 = 56414418

DIVISION

Division 8(7) 8(7) 8(7) 3/6/18 to 2/3/19.

SUB-DIVISION

357 dt 7/6/18

MEASUREMENT BOOK

2nd Floor. 1st floor. 2nd floor.



# Abstract of Cost

79

Sch. XLV-Form No. 134

| Particulars                                            | Details of actual measurement |    |    |    | Contents of area |
|--------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                        | No.                           | L. | B. | D. |                  |
| ① Restoration of rainents<br>with Soil — E/I           |                               |    |    |    |                  |
| 50.67m <sup>3</sup> O.V.T M.B P — (76)                 |                               |    |    |    | 17657.00         |
| @ 348.47/m <sup>3</sup> — Rs.                          |                               |    |    |    | 7523.00          |
| ② Making up of Berms/<br>Shoulder — E/I                |                               |    |    |    |                  |
| 154.72m <sup>2</sup> O.V.T M.B P — (77)                |                               |    |    |    |                  |
| @ 51.40/m <sup>2</sup> — Rs.                           |                               |    |    |    | 7953.00          |
| ③ Repair of pot holes<br>filled with 75mm WBM<br>— E/I |                               |    |    |    |                  |
| 35.83m <sup>2</sup> O.V.T M.B P — (77)                 |                               |    |    |    |                  |
| @ 416.89/m <sup>2</sup> — Rs.                          |                               |    |    |    | 14937.00         |
| ④ Patch repair over<br>pot holes with 200mm — E/I      |                               |    |    |    |                  |
| 35.83m <sup>2</sup> O.V.T M.B P — (77)                 |                               |    |    |    |                  |
| @ 277.13/m <sup>2</sup> — Rs.                          |                               |    |    |    | 9930.00          |
| ⑤ Patch repair over<br>Bituminous Surface — E/I        |                               |    |    |    |                  |
| 35.84m <sup>2</sup> O.V.T M.B P — (78)                 |                               |    |    |    |                  |
| @ 299.60/m <sup>2</sup> — Rs.                          |                               |    |    |    | 10738.00         |
| ⑥ Maint <sup>n</sup> of H.P<br>Culverts — E/I          |                               |    |    |    |                  |
| 2.00 Nos O.V.T M.B P — (78)                            |                               |    |    |    |                  |
| @ 1098.11/each — Rs.                                   |                               |    |    |    | 2196.00          |
| ⑦ Maint <sup>n</sup> of Road<br>Sign — E/I             |                               |    |    |    |                  |

Continuation

Continuation