कार्यपालक अभियन्ता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमण्डल, वक्सर

чліт...575./

वक्सर, दिनांक

प्रेषक:-

कार्यपालक अभियन्ता, ग्रामीण कार्य विभाग, कार्य प्रमण्डल, वक्सर।

सेवा में,

नोडल पदाधिकारी, 3054 (M.R) कोषांग, बिहार, पटना।

विषय:- शीर्ष 30

शीर्ष 3054 नई अनुरक्षण नीति-2018 अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अन्तर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेत् राशि की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित राशि उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यों का विपत्र भुगतान किया जा सके।

अनु0:- (1) अधियाचना प्रपत्र

(2) IRI Value Report

(3) Map

(4) प्रमाण-पत्र।

विश्वासभाजन

ार्व १० ४ · 25 कार्यपालक अभियन्ता

ग्रा०का०वि०, कार्य प्रमण्डल,

FORM GFR 19-A

(See Government of India's Decision (I) below Rule- 150) Form of Utilization Certificate upto date of 16.04,2025

Name of Scheme :- MR NEW MAINTENANCE POLICY-2018.

SI. No.	Name of Scheme	Sanction No. & Date with Amount (Rs.In lacs)	Amount Received (Rs.In Lacs)	Particulars
	•	Through C.F.M.S. Received		
1	MR NEW MAINTENA NCE POLICY- 2018.	BF up to 2024-2025 Lt No-29 dt-30.03.2025 12741.89335	12741.89335	Certified that Alltoment Received during the year 2024- 2025 Throught C.F.M.S. Rs.12741.89335 lacs of grants- in-favour of Executive Engineer, R.W.D.(W) Division, Buxar. Bihar a sum of Rs.12718.77567 lacs has been utilized for the purpose of MR NEW MAINTENANCE POLICY- 2018. schemes as given in the margin for which it was sanctioned and that the balance of Rs.23.11788 lacs (allotment surrender vide It no- 460 dt- 21.03.2025 amount Rs.17.76709) remaining unutilized at the end of the period under report.
		Total Rs. =	12741.89335	

2 Certified that I have satisfied myself that the conditions on which the grants- in - aid was sanctioned have been duly fulfilled, are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercise:-

- i) Works have been supervised by Executive Engineer/ Superintending Engineer
- ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- iii) Construction materials have been tested.
- iv) Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v) All other codal formalities have been observed.
- 3 Physical progress achieved:
 - i) Construction of Road works.
 - ii) Construction of CD works.

R.W.D. (W) Division.

Buxar

Executive Engineer R.W.D. (W) Division.

Buxar

Name of Division:- RWD Works Division Buxar.

No.

) car

Name of Road

Name of Contractor (In English)

Project Id

Administrative Sanction

Agreement Amount (In Lacs)

Value of IRI Thickness of Bitimen (in Layer mm/km) (lú mm)

Bitumen Content in Percentage Value of

Allotment Received (in Lacs)

Expenditure as per MIS (in Lacs)

Measurment (in Lacs)

Value of

Current
Dentand
(in Lacs)

Remarks

Total

89

2023-24

PANDEYPATTI SIV KAILESH
MANDIR TO SANDEEP GON,
LAXSHMAN RAI KE GHAR HOTE
HUE MTASY POKHRA TAK

Narendra Kumar

10401912018

1.200

59.24400

29.82479

6.00010

2070

25

5%

0.00000

0.00000

29.82479

29.82479

Physically complete

MR NEW MAINTENANCE POLICY-2018. ALLOTMENT REQUISITION

Rural Works Department

7

D.A.O Brand Was

My 18

Executive Engineer
RWD Works Division
River

Date-16.04.2025

कार्यपालक अभिंयता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर

कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत PANDEYPATTI SIV KAILESH MANDIR TO SANDEEP GON, LAXSHMAN RAI KE GHAR HOTE HUE MTASY POKHRA TAK पथ का कार्य गुणवत्ता एंव विश्ष्टियों के अनुरुप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, सहायक अभियंता द्वारा 50 प्रतिशत एंव कनीय अभियंता के द्वारा शत् प्रतिशत किया गया है।

कनीय अभियंता ग्रामीण कार्य विभाग कार्य प्रशाखा बक्सर

सहायक अभियंता ग्रामीण कार्य विभाग कार्य अवर प्रमंडल बक्सर ्र १० ४-२५ कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल, बक्सर

Name of Road:-PANDEYPATTI SIV KAILESH MANDIR TO SANDEEP GON, LAXSHMAN RAI KE GHAR HOTE HUE MTASY POKHRA TAK Contractor Name:-Narendra Kumar

Kartan K	15/4/25 13:43:	15/4/25 13:42:	15/4/25 13:41:	15/4/25 13:40:	15/4/25 13:40:	15/4/25 13:37:	15/4/25 13:36:5	15/4/25 13:35:2	15/4/25 13:34:2	15/4/25 13:34:1	15/4/25 13:33:33	15/4/25 13:32:0		Date Time
													No.	Section
Tearly 1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	in km	Length
\$ \$\frac{1}{2}\$	250	230	240	210	210	20p	250	200	200	220	240	230	in mm	Bumps
	10.1	10.1	10.1	10.1	10.1	10.1	10.1	10.1	10.1	10.1	10.1	10.1	Rate	Speed
7	2500	2300	2400	2100	2100	2000	2500	2000	2000	2200	2400	2300	mm/km	OR
A E A E	2288	2125	2207	1962	1962	1880	2288	1880	1880	2044	2207	2125	mm/km	Z
<i>م ا</i>	۵	G	<u>ه</u>	G	ດ	G	G	G	G	മ	G	<u>ه</u>	ROAD	:ATEGORY
E 1.75	25.55551	25.55543	25.55546	25.5554	25.5556	25.55558	25.55564	25.55603	25.55645	25.55647	25.55651 83.986703	25.55656		Latitude
Ϋ́,	33.978901	83.981657	83.982506	83.983254	83.98399	83.984842	83.98565	83.985733	83.98595	83.986304	83.986703	83.9871		atitude Longitude
	Normal	Normal			Normal	Normal <4000	Normal Good			Normal		Normal		e Event
			Normal Machine ID=19195	Normal IRI value=2070		<4000 4001-5000 >5001	Good Average Poor	Normal (R) RURAL ROAD			Normal $Y = 2044$	X = 2125	$Y = 0 * X ^2 + 0.816 * X + 249$	

