


Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
14 Year Maintenance Work					
ABSTRACT OF COST					
① Restoration of Reinforced					
with steel etc. comp. as					
Per TD					
Qty vide ^{No-1940} comp , Pg No-09-					
10, item No-1.					
8.43 m ³ .					
@ Rs 416.11/m ³					Rs 3508.42
② Making up of berms					
stripping loose soil from					
the shoulder etc. comp					
As Per TD					
Qty vide ¹⁹⁴⁰ comp , Pg No-10,					
item No-2					
45.25 m ²					
Unit @ 45.00 m ²					
@ Rs 59.48/m ²					Rs 2672.00
③ Repair over bituminous					
surface, 20mm M.S.C. etc.					
Comp. As Per TD					
Qty vide ^{No-1940} comp , item					
No-3, Pg No-10-11.					
4.89 m ²					
@ Rs 226.88/m ²					Rs 1110.42
Continuation					G/L Rs 7295.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					By CR 2295.00
④ Repair of RCC Railing					
the comp. as per T.C.					
Qty vide MB No-1940					
Item No-4, Pg No-11.					
198.16 m					
Limit 19.62 m					
@ R 2513.69/m					CR 49,319.00
					- R 56,614.00
Limit -					R 56,608.00
Add GST @ 18% of T.C. R					10,191.00
Add CC @ 10% of T.C. R					566.00
Add CP					R 200.00
					- R 62,585.00
Less 0.25% below R					
Per A/E					R 169.00
Payable amount.					- R 62,796.00
					
25/03/25					
JE.					
					
25/3/25					
A/E					

Continuation