

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, बक्सर

पत्रांक...580/

बक्सर, दिनांक 17-04-25/

प्रेषक:-

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बक्सर।

सेवा में,

नोडल पदाधिकारी,
3054 (M.R) कोषांग,
बिहार, पटना।

विषय:- शीर्ष 3054 नई अनुरक्षण नीति-2018 अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अन्तर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु राशि की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित राशि उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यों का विपत्र भुगतान किया जा सके।

- अनु०:- (1) अधियाचना प्रपत्र
(2) IRI Value Report
(3) Map
(4) प्रमाण-पत्र।

विश्वासभाजन

(P)

17-4-25

कार्यपालक अभियन्ता
ग्रा०का०वि०, कार्य प्रमण्डल,

बक्सर

Om
17-4-25

FORM GFR 19-A

(See Government of India's Decision (I) below Rule- 150)
Form of Utilization Certificate upto date of 17.04.2025

Name of Scheme :- MR NEW MAINTENANCE POLICY-2018.

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (Rs.In lacs)	Amount Received (Rs.In Lacs)	Particulars
Through C.F.M.S. Received			-	
1	MR NEW MAINTENANCE POLICY-2018.	<u>BF up to 2024-2025</u> <u>Lt No-29 dt-30.03.2025</u> <u>12741.89335</u>	12741.89335	Certified that Allotment Received during the year 2024-2025 Through C.F.M.S. Rs.12741.89335 lacs of grants-in- favour of Executive Engineer, R.W.D.(W) Division, Buxar. Bihar a sum of Rs.12718.77567 lacs has been utilized for the purpose of MR NEW MAINTENANCE POLICY-2018. schemes as given in the margin for which it was sanctioned and that the balance of Rs.23.11788 lacs (allotment surrender vide Lt no-460 dt- 21.03.2025 amount Rs.17.76709) remaining unutilized at the end of the period under report.
Total Rs. =			12741.89335	


- 2 Certified that I have satisfied myself that the conditions on which the grants- in - aid was sanctioned have been duly fulfilled. are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercise:-


- i) Works have been supervised by Executive Engineer/ Superintending Engineer
- ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- iii) Construction materials have been tested.
- iv) Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v) All other codal formalities have been observed.

3 **Physical progress achieved:-**

- i) Construction of Road works.
- ii) Construction of CD works.


D.A.O.
R.W.D. (W) Division.
Buxar


17.4.25
Executive Engineer
R.W.D. (W) Division.
Buxar


17.4.25

Name of Division:- RWD Works Division Buxar.

Rural Works Department
MIR NEW MAINTENANCE POLICY-2018. ALLOTMENT REQUISITION

Date-17.04.2025

Sl. No.	Year	Name of Road	Name of Contractor (In English)	Project Id	Administrative Sanction		Agreement Amount (In Lacs)		Value of RRI (in million)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (in Lacs)	Current Demand (in Lacs)	Remarks
94	2023-24	1068-AHIRAULI GARANI ROAD TO ARJUNPUR HARIAN TOLA (VR68)	Narendra Kumar	10401902133	0.860	35.65100	17.40047	4.59215	2025	25	5%	0.00000	0.00000	17.40047	17.40047	Physically complete

RWD Works Division
Buxar

Executive Engineer
RWD Works Division
Buxar


(Signature)

17.4.25


कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर

कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत L068-AHIRAULI GARANI ROAD TO ARJUNPUR HARIJAN TOLA (VR68) पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, सहायक अभियंता द्वारा 50 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।


कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य प्रशाखा बक्सर


17/04/25
सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल बक्सर


17.4.25
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

Name of Road:-Bairi - 1068-AHIRAULI GARANI ROAD TO ARJUNPUR HARIJAN TOLA (VR68) Contractor Name:-Narendra Kumar

Date	Time	Section	Length	Bumps	Speed	OR	IRI	ATEGORY	Latitude	Longitude	Event	
16/4/25	11:03:15	No.	in km	in mm	Rate	mm/km	mm/km	ROAD				
16/4/25	11:04:41	66	0.1	200	10.1	2000	1880	G	25.594897	84.011252	Normal	$Y = 0 * X^2 + 0.816 * X + 249$
16/4/25	11:05:13	66	0.1	210	20.2	2100	1962	G	25.595683	84.011011	Normal	X = 2125
16/4/25	11:06:07	66	0.1	210	20.2	2100	1962	G	25.596564	84.01099	Normal	Y = 2044
16/4/25	11:08:01	66	0.1	260	20.2	2600	2370	G	25.596997	84.011352	Normal	
16/4/25	11:09:03	66	0.1	230	10.1	2300	1962	G	25.59716	84.01213	Normal	(R) RURAL ROAD
16/4/25	11:10:25	66	0.1	110	10.1	2200	2044	G	25.597518	84.012785	Normal	Good Average Poor
16/4/25	11:11:01	66	0.1	210	10.1	2100	1962	G	25.597699	84.013215	Normal	<4000 4001-5000 >5001
16/4/25	11:12:51	66	0.06	210	10.1	2100	1962	G	25.59793	84.014997	Normal	IRI value=2025
		Length	0.860									Machine ID=19195

Kuldeep
19.4.25


SR 17/4/25

8/17/04/25
4E

17.4.25
EE

File : C:\Users\7SURYANAND MISHRA\Desktop\060313561.xlsx Section No. : 66, Eqn : test

Name of Customer : narendra kumar, Name of Work/ Road : L068- ahirauli garani road to arjunpur harijan tola, Lab



Kaushal km
12.04.2025
SE 12/4/25
AE
17/04/25
EE