

कार्यपालक अभियन्ता का कार्यालय  
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, बक्सर

पत्रांक 583 /

बक्सर, दिनांक 17.4.25 /

प्रेषक:-

कार्यपालक अभियन्ता,  
ग्रामीण कार्य विभाग,  
कार्य प्रमण्डल, बक्सर।

सेवा में,

नोडल पदाधिकारी,  
3054 (M.R) कोषांग,  
बिहार, पटना।

विषय:- शीर्ष 3054 नई अनुरक्षण नीति-2018 अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अन्तर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु राशि की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित राशि उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यों का विपत्र भुगतान किया जा सके।

- अनु०:- (1) अधियाचना प्रपत्र  
(2) IRI Value Report  
(3) Map  
(4) प्रमाण-पत्र।

विश्वासभाजन



17.4.25

कार्यपालक अभियन्ता  
ग्रा०का०वि०, कार्य प्रमण्डल,  
बक्सर

  
17-4-25

**FORM GFR 19-A**

(See Government of India's Decision (I) below Rule- 150)

Form of Utilization Certificate upto date of 17.04.2025

**Name of Scheme :- MR NEW MAINTENANCE POLICY-2018.**

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (Rs.In lacs)	Amount Received (Rs.In Lacs)	Particulars
Through C.F.M.S. Received			-	
1	MR NEW MAINTENANCE POLICY 2018.	BF up to 2024-2025 Lt No-29 dt-30.03.2025 <b><u>12741.89335</u></b>	<b>12741.89335</b>	Certified that Allotment Received during the year 2024-2025 Through C.F.M.S. Rs.12741.89335 lacs of grants-in- favour of Executive Engineer, R.W.D.(W) Division, Buxar. Bihar a sum of <b>Rs.12718.77567 lacs</b> has been utilized for the purpose of MR NEW MAINTENANCE POLICY-2018. schemes as given in the margin for which it was sanctioned and that the balance of <b>Rs.23.11788 lacs (allotment surrender vide Lt no-460 dt- 21.03.2025 amount Rs.17.76709)</b> remaining unutilized at the end of the period under report.
		<b>Total Rs. =</b>	<b>12741.89335</b>	

- 2 Certified that I have satisfied myself that the conditions on which the grants- in - aid was sanctioned have been duly fulfilled. are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

**Kind of Checks exercise:-**

- Works have been supervised by Executive Engineer/ Superintending Engineer
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formalities have been observed.

3 **Physical progress achieved:-**

- Construction of Road works.
- Construction of CD works.

  
D.A.O  
R.W.D. (W) Division,  
Buxar

  
17.4.25  
Executive Engineer  
R.W.D. (W) Division,  
Buxar

  
17.4.25

Name of Division:- RWD Works Division Buxar.

Rural Works Department  
MR NEW MAINTENANCE POLICY-2018. ALLOTMENT REQUISITION

Date-17.04.2025

Date-17/04/2025																
Sl. No.	Year	Name of Road	Name of Contractor (In English)	Project Id	Administrative Sanction		Agreement Amount (In Lacs)	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (In Lacs)	Current Demand (in Lacs)	Remarks	
161	2023-24	Churamanpur Siv Mandir To Panchayat Bhawan Hote Huye Baban Pandey ke Char Tak koiri tola	Narendra Kumar	10401912025	0.700	40.85700	20.96699	2.22520	2087	25	5%	0.00000	0.00000	20.96699	20.96699	Physically complete

D.A.O  
RWD Works Division  
Buxar


Executive Engineer  
RWD Works Division  
Buxar


17.4.25  
17.4.25


कार्यपालक अभियंता का कार्यालय  
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर

कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत Churamanpur Siv Mandir To Panchayat Bhawan Hote Huye Baban Pandey ke Ghar Tak koiri tola. पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, सहायक अभियंता द्वारा 50 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।

  
कनीय अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रशाखा बक्सर

  
17/04/25  
सहायक अभियंता  
ग्रामीण कार्य विभाग  
कार्य अवर प्रमंडल बक्सर

  
17.4.25  
कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमंडल, बक्सर

Name of Road:-Churamanpur Shiv Mandir To Panchayat Bhawan Hote Huve Baban Pandey ke Ghar Tak koiri tola  
Contractor Name:-Narendra Kumar

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	QR mm/km	IRI mm/km	ATEGORY ROAD	Latitude	Longitude	Event
17/4/25	12:03:15	68	0.1	200	10.1	2000	1880	G	25.58979	84.022802	Normal
17/4/25	12:04:21	68	0.1	210	20.2	2100	1962	G	25.59048	84.02344	Normal
17/4/25	12:05:03	68	0.1	210	20.2	2100	1962	G	25.59047	84.023398	Normal
17/4/25	12:06:07	68	0.1	260	20.2	2600	2370	G	25.59078	84.023314	Normal
17/4/25	12:08:01	68	0.1	210	10.1	2100	1962	G	25.59077	84.023068	Normal
17/4/25	12:09:03	68	0.1	230	10.1	2300	2125	G	25.59156	84.023229	Normal
17/4/25	12:10:05	68	0.1	110	10.1	2200	2044	G	25.59156	84.023517	Normal
Length 0.700											

$$Y = 0 * X^2 + 0.816 * X + 249$$

$$X = 2125$$

$$Y = 2044$$

(R) RURAL ROAD

Normal Good Average Poor

Normal <4000 4001-5000 >5001

IRI value=2087

Machine ID=19195

Km 5.14/100  
17.04.25


5011/11/25

17/04/25  
AE

17.4.25  
EE

File : C:\Users\7SURYANAND MISHRA\Desktop\06031355.xlsx Section No. : 68, Eqn : test

Name of Customer : narendra kumar, Name of Work / Road : Churamanpur siv mandir to Panchayat bhawan hote huye



Kampan  
13.0.0.0.0

Quesar  
50 11/11/15

8/17/04/25  
AE

17.4.25  
EE