

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल, बेनीपट्टी।

पत्रांक.....727

दिनांक.....27.04.2025

प्रेषक, कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी।

सेवा में,
अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
ग्रामीण कार्य विभाग,
बिहार, पटना।


विषय:— शीर्ष **NEW MAINTENANCE POLICY – 2018 (MR – 3054)** में आवंटन उपलब्ध कराने के संबंध में।

महाशय,
उपरोक्त विषय के संबंध में कहना है शीर्ष **NEW MAINTENANCE POLICY – 2018 (MR-3054)** अन्तर्गत पथ में संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय ताकि संवेदक का भुगतान किया जा सके।

अनु०:—

1. अधियाचना प्रमाण पत्र 1 पृष्ठ में।
2. उपयोगिता प्रमाण पत्र एक प्रति।

विश्वासभाजन,



कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी।

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilisation Certificate Upto the month of 31 March 2025

New Maintenance policy - 2018

PIU – Executive Engineer, R.W.D (W) Division, Benipatti

SL. No	Name of Sachem	Sanction No. & Date with Amount (In Rs. lacs)	Amount Received (In Rs. lacs)	Particulars
1	Construction of Rural roads under New maintenance policy - 2018	Authorization letter No. 29 we dt-30.03.2025 Rs.444.81488 Lakh	4434.73317	Certified that out of Rs. 4434.73317 Lakh received during the years up to 2024-25 (31 March 2025) in favour of Ex. Engineer, RWD (W) Division Benipatti, Madhubani, Bihar, a sum of Rs. 4413.78816 Lakh has been utilized for the purpose of New maintenance policy-2018 as given in the margin for which the balance of Rs 20.94501 Lakh remaining unutilized at the end of the period under.

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- I. Works have been supervised by Executive Engineer/Superintending Engineer.
- II. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- III. Construction materials have been tested.
- IV. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- V. All other codal formalities have been observed.

3. Physical Progress achieved:-

- I. Construction of Road Works.
- II. Construction of CD Works.


**Divisional Account Officer,
R.W.D (W) Division
Benipatti**


**Executive Engineer
R.W.D (W) Division
Benipatti**

Formate of Requisition under Head New Maintenance policy - 2018 (MR- 3054) for the month of April-2025

Name of Division :- Benipatti

Sl No.	Package No.	Name of road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of BBI (in m/cu)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (In km)	Amount of (in lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RAMNA, BEN/24/0005	Madhubani Jila Antargat Benipatti Prakhanda me Bhairava Se Sakrati PMGISY Road Tak Path Nirman	31910003009	1086/ 01.03.2024	1.720	118.69800	108.62096	7.81502	25MBD/2024-25 13.08.2024	12.05.2025	23.01.2025	2336	25	5	56.14889	56.14889	47.92803	Work Completed
Total					1.720	118.69800	108.62096	7.81502	—	—	—	2336	25	5	56.14889	56.14889	47.92803	


Divisional Account Officer,
R.W.D(W)Div. Benipatti


Executive Engineer
R.W.D(W)Div. Benipatti
21/04/25

OFFICE OF THE EXECUTIVE ENGINEER
RWD WORKS DIVISION
BENIPATTI

Name of Scheme:- Madhubani Jila Antargat Benipatti Prakhanda me Bhairava Se Sakrati PMGSY Road Tak Path
Nirman, Package No. - RM/MA/BEN/24/0006
Project ID - 31910003009


Certified that all item wise 100% measurement has been taken by me	Certified that all item wise 50% measurement has been Checked by me	Certified that all item wise 10% measurement has been Checked by me
--	---	---


Junior Engineer
RWD Work Section Bisfi
Works Division Bisfi


Assistant Engineer
RWD Work Sub Division Bisfi
Works Division Bisfi


Executive Engineer
RWD Works Division
Benipatti

File : C:\Users\PRWD\OneDrive\Desktop\SBS\19031832.Xls, Section No. : 49, Eqn : $Y = 0.0001X^2 + 0.989X - 13.58$
 Name of Customer : Sbs Engicon Private Limited, Name of Work/ Road : Madhubani jila antargat benipatti prkhand



Handwritten signature and date: 20/12/20

Handwritten signature and date: 20/12/20

Handwritten signature and date: 20/12/20

Name Of Road:-Madhubani jila antargat benipatti prkhand me bhairava se sakradi PMGSY road tak path nirman												
Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI In MM/Km	CATEG ORY	Latitude	Longitu de	Event	
30/1/25	12:35:5	49	0.1	230	10.1	2300	2261 G	ROAD	26.34749	85.88061	Normal	
30/1/25	12:35:5	49	0.1	250	20.2	2500	2458 G		26.34744	85.88133	Normal	
30/1/25	12:36:16	49	0.1	210	20.2	2100	2063 G		26.34741	85.88244	Normal	
30/1/25	12:36:16	49	0.1	230	20.2	2300	2261 G		26.34742	85.88341	Normal	
30/1/25	12:36:51	49	0.1	220	10.1	2200	2162 G		26.3474	85.88429	Normal	
30/1/25	12:37:26	49	0.1	260	20.2	2600	2557 G		26.34725	85.88525	Normal	
30/1/25	12:37:26	49	0.1	230	20.2	2300	2261 G		26.34716	85.88621	Normal	
30/1/25	12:38:1	49	0.1	250	20.2	2500	2458 G		26.34721	85.88712	Normal	
30/1/25	12:38:1	49	0.1	230	20.2	2300	2261 G		26.34705	85.88798	Normal	
30/1/25	12:38:37	49	0.1	220	10.1	2200	2162 G		26.34701	85.88884	Normal	
30/1/25	12:39:0	49	0.1	260	20.2	2600	2557 G		26.34717	85.88993	Normal	
30/1/25	12:39:12	49	0.1	260	20.2	2600	2557 G		26.34739	85.89064	Normal	
30/1/25	12:39:47	49	0.1	250	20.2	2500	2458 G		26.3477	85.89139	Normal	
30/1/25	12:40:0	49	0.1	220	10.1	2200	2162 G		26.34812	85.89257	Normal	
30/1/25	12:40:23	49	0.1	250	20.2	2500	2458 G		26.34799	85.89317	Normal	
30/1/25	12:41:0	49	0.1	250	20.2	2500	2458 G		26.34716	85.89332	Normal	
30/1/25	12:41:0	49	0.1	220	10.1	2200	2162 G		26.34717	85.89333	Normal	
Avg							2336.23					

$$Y = 0 * X^2 + 0.989 * X - 13.58$$

$$X = 2200$$

$$Y = 2162$$

(R) RURAL ROAD

Good <4000
Average 4001-5000
Poor >5001

26/1/25

26/1/25

26/1/25

Place of seed - maddhubai dalle and 250000 Bupathi paves
Sachar and Pithay paves Telpal vinery

Schedule XLV-Form No. 134

S.B.S Engicom Pvt. Ltd.

BRHPPA/11 DIVISION

BJS/24 SUB-DIVISION

KB/140-1458

MEASUREMENT BOOK

MIR 3054

Find on Arc. Am' 11

7

Sch. XLV—Form No. 134

[illegible]

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Railway Station					
and 2) - 28.90 m					
Conc'd 10.75 m					6739.00
				DS	8677410.00
ADD GST 18%				DS	1561734.00
Less 1%				al	8677410.00
S. Fee				DS	93035.00
				DS	10417153.00
Less 0.11% Balen				Q	11461.00
					10407692.00
Less 0.11% Balen					5614889.00
					4792803.00

22/4/25
SC

22/4/25
AE

Continuation